
Errata: CS4270 Rev C0 Silicon

Reference CS4270 Data Sheet DS686PP1

- ◆ Measured DAC THD+N (0 dB) with VA = 5 V or 3.3 V (nominal voltage) could be -81 dB and does not meet the -83 dB maximum specification in the Data Sheet. Measured DAC THD+N (0 dB) with VA = 3.0 V (3.3 V min.) is -79 dB and does not meet the -83 dB maximum specification in the Data Sheet.
- ◆ The digital portions of the part (both ADC and DAC) will not function when MCLK divide by 1.5 is selected and VD = 3.3 V. The following start-up sequences will correct the problem.

In Control Port Mode:

- Power-up the part
- Hold MCLK Static
- Hard reset the part
- Set PDN
- Set the Ratio Select bits in Reg. 03h
- Release PDN

In Stand-Alone Mode:

- Power-up the part
- Hold the part in reset
- Set the MDIV1,2 pin logic levels
- Release reset

Contacting Cirrus Logic Support

For all product questions and inquiries, contact a Cirrus Logic Sales Representative.

To find the one nearest you, go to <http://www.cirrus.com>