

Automotive Silicon Errata and Data Sheet Clarifications

ATtiny202/204/402/404/406 Automotive



The ATtiny202/204/402/404/406 Automotive devices you have received conform functionally to the current device data sheet (www.microchip.com/DS40002159), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATtiny202/204/402/404/406 Automotive devices.

Notes:

- This document summarizes all the silicon errata issues from all the silicon revisions, previous and current
- Refer to the Device/Revision ID section in the current device data sheet (www.microchip.com/DS40002159) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. B ⁽¹⁾	Rev. C
Device	2.2.1. Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values	X	X
	2.2.2. Write Operation Lost if Consecutive Writes to Specific Address Spaces	X	X
ADC	2.3.1. One Extra Measurement Performed After Disabling ADC Free-Running Mode	X	X
	2.3.2. ADC Functionality Cannot be Ensured with CLKADC Above 1.5 MHz and a Setting of 25% Duty Cycle	X	X
	2.3.3. Pending Event Stuck When Disabling the ADC	X	X
CCL	2.4.1. Connecting LUTs in Linked Mode Requires OUTEN Set to '1'	X	X
	2.4.2. D-latch is Not Functional	X	X
	2.4.3. The CCL Must be Disabled to Change the Configuration of a Single LUT	X	X
NVMCTRL	2.5.1. Wrong Reset Value of NVMCTRL.CTRLA Register	X	X
PORTMUX	2.6.1. Selecting Alternative Output Pin for TCA0 Waveform Output 0-2 also Changes Waveform Output 3-5	X	X
RTC	2.7.1. Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler Counter	X	X
	2.7.2. Disabling the RTC Stops the PIT	X	X
TCA	2.8.1. Restart Will Reset Counter Direction in NORMAL and FRQ Mode	X	X
TCB	2.9.1. Minimum Event Duration Must Exceed the Selected Clock Period	X	X
	2.9.2. The TCA Restart Command Does Not Force a Restart of TCB	X	X
	2.9.3. CCMP and CNT Registers Act as 16-Bit Registers in 8-Bit PWM Mode	X	X
USART	2.10.1. TXD Pin Override Not Released When Disabling the Transmitter	X	X
	2.10.2. Frame Error on a Previous Message May Cause False Start Bit Detection	X	X
	2.10.3. Full Range Duty Cycle Not Supported When Validating LIN Sync Field	X	X
	2.10.4. Open-Drain Mode Does Not Work When TXD is Configured as Output	X	X

Note:

1. This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 Device

2.2.1 Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values

Writing the OSCLOCK fuse in FUSE.OSCCFG to '1' prevents the automatic loading of calibration values from the signature row. The device will run with an uncalibrated OSC20M oscillator.

Work Around

Do not use OSCLOCK for locking the oscillator calibration value. The oscillator calibration value can be locked by writing LOCKEN in CLKCTRL.MCLKLOCK to '1' when using the OSC20M oscillator as the Main Clock source.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.2.2 Write Operation Lost if Consecutive Writes to Specific Address Spaces

An ST/STD/STS instruction to address ≥ 64 followed by an ST/STD instruction to address < 64 or SLPCTRL.CTRLA register will cause loss of the last write.

Work Around

To avoid loss of write operation, use one of the following workarounds depending on address space:

- Insert an NOP instruction before writing to address < 64 , or use the OUT instruction instead of ST/STD
- Insert an NOP instruction before writing to SLPCTRL.CTRLA register

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.3 ADC - Analog-to-Digital Converter

2.3.1 One Extra Measurement Performed After Disabling ADC Free-Running Mode

The ADC may perform one additional measurement after clearing ADCn.CTRLA.FREERUN.

Work Around

Write ADCn.CTRLA.ENABLE to '0' to stop the Free-Running mode immediately.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.3.2 ADC Functionality Cannot be Ensured with CLK_{ADC} Above 1.5 MHz and a Setting of 25% Duty Cycle

The ADC functionality cannot be ensured if CLK_{ADC} > 1.5 MHz with ADCn.CALIB.DUTYCYC set to '1'.

Work Around

If ADC is operated with $CLK_{ADC} > 1.5 \text{ MHz}$, `ADCn.CALIB.DUTYCYC` must be set to '0' (50% duty cycle).

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.3.3 Pending Event Stuck When Disabling the ADC

If the ADC is disabled during an event-triggered conversion, the event will not be cleared.

Work Around

Clear `ADC.EVCTRL.STARTEI` and wait for the conversion to complete before disabling the ADC.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.4 CCL - Configurable Custom Logic**2.4.1 Connecting LUTs in Linked Mode Requires OUTEN Set to '1'**

Connecting the LUTs in linked mode requires `LUTnCTRLA.OUTEN` set to '1' for the LUT providing the input source.

Work Around

Use an event channel to link the LUTs, or do not use the corresponding I/O pin for other purposes.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.4.2 D-latch is Not Functional

The CCL D-latch is not functional.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.4.3 The CCL Must be Disabled to Change the Configuration of a Single LUT

The CCL peripheral must first be disabled (write `ENABLE` in `CCL.CTRLA` to '0') to reconfigure a LUT. Writing `ENABLE` to '0' will disable all the LUTs and affect the LUTs not under reconfiguration.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.5 NVMCTRL - Nonvolatile Memory Controller

2.5.1 Wrong Reset Value of NVMCTRL.CTRLA Register

In some cases, the NVMCTRL.CTRLA reset value will not be '0x00'. Even reserved bits can be read as '1' after Reset.

Work Around

Ignore the initial value.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.6 PORTMUX - Port Multiplexer

2.6.1 Selecting Alternative Output Pin for TCA0 Waveform Output 0-2 also Changes Waveform Output 3-5

Selecting the alternative output pin for TCA0 in PORTMUX.CTRLA does not work as described when TCA0 operates in split mode.

- Writing PORTMUX.CTRLA bit 0 to '1' will shift the pin position for both WO0 and WO3
- Writing PORTMUX.CTRLA bit 1 to '1' will shift the pin position for both WO1 and WO4
- Writing PORTMUX.CTRLA bit 2 to '1' will shift the pin position for both WO2 and WO5

PORTMUX.CTRLA[5:3] are non-functional.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

Note: Not applicable to 8-pin devices.

2.7 RTC - Real-Time Counter

2.7.1 Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler Counter

Any write to the RTC.CTRLA register resets the 15-bit prescaler counter. The next count occurs $\frac{1}{2}$ prescaler period after the reset, resulting in a period length of 0.5 to 1.5 times the expected period, depending on when the reset occurs.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.7.2 Disabling the RTC Stops the PIT

Writing RTC.CTRLA.RTCEN to '0' will stop the PIT.

Writing RTC.PITCTRLA.PITEN to '0' will stop the RTC.

Work Around

Do not disable the RTC or the PIT if any of the modules are used.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.8 TCA - Timer/Counter A**2.8.1 Restart Will Reset Counter Direction in NORMAL and FRQ Mode**

When the TCA is configured to the NORMAL or FRQ mode (WGMODE in TCAn.CTRLB is '0x0' or '0x1'), a RESTART command or Restart event will reset the direction to default. The default is counting upwards.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.9 TCB - Timer/Counter B**2.9.1 Minimum Event Duration Must Exceed the Selected Clock Period**

Event detection will fail if TCBn receives an input event with a high/low period shorter than the period of the selected clock source (CLKSEL in TCBn.CTRLA). This applies to the TCB modes (CNTMODE in TCBn.CTRLB) *Time-Out Check* and *Input Capture Frequency and Pulse-Width Measurement*.

Work Around

Ensure that the high/low period of input events is equal to or longer than the selected clock source (CLKSEL in TCBn.CTRLA) period.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.9.2 The TCA Restart Command Does Not Force a Restart of TCB

The TCA restart command does not force restarting the TCB when TCB is running in SYNCUPD mode. TCB is restarted only after a TCA OVF.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.9.3 CCMP and CNT Registers Act as 16-Bit Registers in 8-Bit PWM Mode

When the TCB operates in 8-bit PWM mode (CNTMODE in TCBn.CTRLB is '0x7'), the low and high bytes for the CCMP and CNT registers act as 16-bit registers for read and write. They cannot be read or written independently.

Work Around

Use 16-bit register access. Refer to the data sheet for further information.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.10 USART - Universal Synchronous and Asynchronous Receiver and Transmitter**2.10.1 TXD Pin Override Not Released When Disabling the Transmitter**

The USART will not release the TXD pin override if:

- The USART transmitter is disabled by writing the TXEN bit in USART.CTRLB to '0' while the USART receiver is disabled (RXEN in USART.CTRLB is '0')
- Both the USART transmitter and receiver are disabled at the same time by writing the TXEN and RXEN bits in USART.CTRLB to '0'

Work Around

There are two possible work arounds:

- Make sure the receiver is enabled (RXEN in USART.CTRLB is '1') while disabling the transmitter (writing TXEN in USART.CTRLB to '0')
- Writing to any register in the USART after disabling the transmitter will start the USART for long enough to release the pin override of the TXD pin

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.10.2 Frame Error on a Previous Message May Cause False Start Bit Detection

A false start bit detection will trigger if receiving a frame with RXDATAH.FERR set and reading the RXDATAL before the RxD line goes high.

Work Around

Wait for the RxD pin to go high before reading RXDATA by, for instance, polling the bit in PORTn.IN where the RxD pin is located.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.10.3 Full Range Duty Cycle Not Supported When Validating LIN Sync Field

For the LIN sync field, the USART validates each bit to be within $\pm 15\%$ instead of the time between falling edges as described in the LIN specification, which allows a minimum duty cycle of 43.5% and a maximum duty cycle of 57.5%.

Work Around

None.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

2.10.4 Open-Drain Mode Does Not Work When TXD is Configured as Output

When the USART TXD pin is configured as an output, it can drive the pin high regardless of whether the Open-Drain mode is enabled or not.

Work Around

Configure the TXD pin as an input by writing the corresponding bit in PORTx.DIR to '0' when using Open-Drain mode.

Affected Silicon Revisions

Rev. B	Rev. C
X	X

3. Data Sheet Clarifications

Note the following typographic corrections and clarifications for the latest version of the device data sheet (www.microchip.com/DS40002159).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 Memories

3.1.1 Fuses - Factory Default Values

A clarification has been made for the *Fuse Description* section in regards to the fuse default values. The data sheet refers to these values as reset values when they should have been given as factory-programmed values. Also, they are given in both hexadecimal and binary values, which are contradicting each other.

The following sentence has been added to each sub-section of the *Fuse Description* section.

The default value given in this fuse description is the factory-programmed value, and should not be mistaken for the Reset value.

The table below lists the reset values given by the data sheet and the actual factory-programmed default values.

Fuse	Stated Reset Value in Data Sheet		Actual Factory Default on Device	
	Hexadecimal	Binary	Hexadecimal	Binary
WDTCFG	-	`b00000000	0x00	`b00000000
BODCFG	-	`b00000000	0x00	`b00000000
OSCCFG	-	`b0XXXXX01	0x01	`b00000001
SYSCFG0	0xCF	`b11XX01X0	0xF6	`b11110110
SYSCFG1	-	`bXXXXX111	0x07	`b00000111
APPEND	-	`b00000000	0x00	`b00000000
BOOTEND	-	`b00000000	0x00	`b00000000
LOCKBIT	-	`b00000000	0xC5	`b11000101

3.2 Sleep Controller (SLPCTRL)

3.2.1 Sleep Mode Activity Overview

A clarification has been made to Table 12-2 *Sleep Mode Activity Overview*, where the single table has been split into three separate tables for clarity. Functional changes are shown in **bold**.

Table 3-1. Sleep Mode Activity Overview for Peripherals

Peripheral	Active in Sleep Mode		
	Idle	Standby	Power-Down
CPU	-	-	-
RTC	X	X ⁽¹⁾	X ⁽²⁾
WDT	X	X	X
BOD	X	X	X
EVSYS	X	X	X
CCL	X	X ⁽¹⁾	-
ACn			
ADCn			
TCBn			

.....continued

Peripheral	Active in Sleep Mode		
	Idle	Standby	Power-Down
All other peripherals	X	-	-

Notes:

1. The RUNSTBY bit of the corresponding peripheral must be set to enter the active state.
2. **PIT only.**

Table 3-2. Sleep Mode Activity Overview for Clock Sources

Clock Source	Active in Sleep Mode		
	Idle	Standby	Power-Down
Main clock source	X	X ⁽¹⁾	-
RTC clock source	X	X ⁽¹⁾	X ⁽²⁾
WDT oscillator	X	X	X
BOD oscillator⁽³⁾	X	X	X
CCL clock source	X	X⁽¹⁾	-

Notes:

1. The RUNSTBY bit of the corresponding peripheral must be set to enter the active state.
2. **PIT only.**
3. **The BOD oscillator runs only in Sampled mode.**

Table 3-3. Sleep Mode Wake-Up Sources

Wake-Up Sources	Active in Sleep Mode		
	Idle	Standby	Power-Down
PORTx Pin interrupt	X	X	X ⁽¹⁾
BOD VLM interrupt	X	X	X
RTC interrupts	X	X ⁽²⁾	X ⁽³⁾
TWIn Address Match interrupt	X	X	X
USARTn Start-of-Frame interrupt	-	X	-
TCBn interrupts	X	X⁽²⁾	-
ADCn interrupts	X	X ⁽²⁾	-
ACn interrupts	X	X⁽⁴⁾	-
All other interrupts	X	-	-

Notes:


1. **The I/O pin must be configured according to *Asynchronous Sensing Pin Properties* in the PORT section.**
2. The RUNSTBY bit of the corresponding peripheral must be set to enter the active state.
3. **PIT only.**
4. **When the RUNSTDBY bit is set, the AC will operate without updating its Status register or triggering interrupts. If another peripheral has requested CLK_PER, the AC will use the clock to update the Status register and trigger interrupts.**

3.3 Universal Synchronous and Asynchronous Receiver and Transmitter (USART)

3.3.1 TXDATA Buffer

The block diagram is missing that USART TX is double-buffered from *Figure 25-1* in the data sheet. The figure below shows the added **TX Buffer**.

Figure 25-1. USART Block Diagram



The following text is changed in the *Overview* section:

The transmitter consists of a **two-level** write buffer.

The following text is changed in the *Data Transmission* section:

The data transmission is initiated by loading the **Transmit Data (USARTn.TXDATAL and USARTn.TXDATAH)** registers with the data to be sent. The data in the **Transmit Data registers are moved to the TX Buffer** once emptied and then to the Shift register once it is empty and ready to send a new frame.

3.4 SPI - Serial Peripheral Interface

3.4.1 SPI Clock

Clarifications regarding the SPI clock have been made in the *Operation - Slave Mode* and *Operation - Slave Mode - Buffer Mode* sections. Functional changes are shown in **bold**.

25.3.2.2 Slave Mode

In Slave mode, the SPI peripheral receives the SPI clock and Slave Select from a Master. Slave mode supports three operational modes: One Normal mode and two configurations for the Buffered mode. In Slave mode, the control logic will sample the incoming signal on the SCK pin. **To ensure correct sampling of this clock signal, the minimum low and high periods must each be longer than two peripheral clock cycles.**

25.3.2.2.3 Buffer Mode

To avoid data collisions, the SPI peripheral can be configured in Buffered mode by writing a '1' to the Buffer Mode Enable (BUFEN) bit in the Control B (SPIn.CTRLB) register. In this mode, the SPI has additional interrupt flags and extra buffers. The extra buffers are shown in *Figure 25-1*. There are two different modes for the Buffer mode, selected with the Buffer mode Wait for Receive (BUFWR) bit. The two different modes are described below with timing diagrams.

Note: When operating as a slave in Buffered mode and the SPI clock is close to maximum frequency, the slave may not be able to set up data in time for the first sample edge during back-to-back transfers. Refer to the *Electrical Characteristics - SPI* section for details.

3.5 Electrical Characteristics

3.5.1 Power Consumption

A clarification of the power consumption in the Power-Down sleep mode has been made to *Table 32-5*. Functional change is shown in **bold**.

Table 32-5. Power Consumption in Power-Down, Standby and Reset Mode

Mode	Description	Condition	Typ. 25°C	Max. 25°C	Max. 85°C ⁽¹⁾	Max. 125°C	Unit
Standby	Standby power consumption	RTC running at 1.024 kHz from internal OSCULP32K $V_{DD} = 3V$	0.7	3.0	6.0	8.0	μA
Power Down/ Standby	Power down/Standby power consumption are the same when all peripherals are stopped	All peripherals stopped $V_{DD} = 3V$	0.1	1.0	5.0	7.0	μA
Reset	Reset power consumption	Reset line pulled down $V_{DD} = 3V$	100	-	-	-	μA

Note:

- These values are based on characterization and are not covered by production test limits.

3.5.2 I/O Pin Characteristics

A clarification of the maximum value of the pull-up resistor is made in *Table 32-15* in the *Electrical Characteristics* section. Functional change is shown in **bold**.

Table 32-15. I/O Pin Characteristics ($T_A = [-40, 105]^{\circ}C$, $V_{DD} = [2.7, 5.5]V$ Unless Otherwise Stated)

Symbol	Description	Condition	Min.	Typ.	Max.	Unit
V_{IL}	Input low-voltage, except RESET pin as I/O		-0.2	-	$0.3 \times V_{DD}$	V
V_{IH}	Input high-voltage, except RESET pin as I/O		$0.7 \times V_{DD}$	-	$V_{DD} + 0.2V$	V
I_{IH} / I_{IL}	I/O pin input leakage current, except RESET pin as I/O	$V_{DD} = 5.5V$, pin high	-	< 0.05	-	μA
		$V_{DD} = 5.5V$, pin low	-	< 0.05	-	
V_{OL}	I/O pin drive strength	$V_{DD} = 3.0V$, $I_{OL} = 7.5$ mA	-	-	0.6	V
		$V_{DD} = 5.0V$, $I_{OL} = 15$ mA	-	-	1	
V_{OH}	I/O pin drive strength	$V_{DD} = 3.0V$, $I_{OH} = 7.5$ mA	2.4	-	-	V
		$V_{DD} = 5.0V$, $I_{OH} = 15$ mA	4	-	-	
I_{total}	Maximum combined I/O sink current per pin group ⁽¹⁾		-	-	100	mA
	Maximum combined I/O source current per pin group ⁽¹⁾		-	-	100	
V_{IL2}	Input low-voltage on RESET pin as I/O		-0.2	-	$0.3 \times V_{DD}$	V
V_{IH2}	Input high-voltage on RESET pin as I/O		$0.7 \times V_{DD}$	-	$V_{DD} + 0.2V$	V
V_{OL2}	I/O pin drive strength on RESET pin as I/O	$V_{DD} = 3.0V$, $I_{OL} = 0.25$ mA	-	-	0.6	V
		$V_{DD} = 5.0V$, $I_{OL} = 0.5$ mA	-	-	1	

.....continued

Symbol	Description	Condition	Min.	Typ.	Max.	Unit
VOH2	I/O pin drive strength on RESET pin as I/O	V _{DD} = 3.0V, I _{OH} = 0.25 mA	2.4	-	-	V
		V _{DD} = 5.0V, I _{OH} = 0.5 mA	4	-	-	
t _{RISE}	Rise time	V _{DD} = 3.0V, load = 20 pF	-	2.5	-	ns
		V _{DD} = 5.0V, load = 20 pF	-	1.5	-	
t _{FALL}	Fall time	V _{DD} = 3.0V, load = 20 pF	-	2.0	-	ns
		V _{DD} = 5.0V, load = 20 pF	-	1.3	-	
CPIN	I/O pin capacitance except TWI pins		-	3	-	pF
CPIN	I/O pin capacitance on TWI pins		-	10	-	pF
R _P	Pull-up resistor		20	35	60	kΩ

Note:

1. Pin group x (Px[7:0]). The combined continuous sink/source current for all I/O ports should not exceed the limits.

3.5.3 SPI - Timing Characteristics

A clarification regarding the SPI clock has been made in *Table 32-17. SPI - Timing Characteristics*. Functional changes are shown in **bold**.

Table 32-17. SPI - Timing Characteristics

Symbol	Description	Condition	Min.	Typ.	Max.	Unit
f _{SCK}	SCK clock frequency	Master	-	-	10	MHz
t _{SCK}	SCK period	Master	100	-	-	ns
t _{SCKW}	SCK high/low width	Master	-	0.5 × t _{SCK}	-	ns
t _{SCKR}	SCK rise time	Master	-	2.7	-	ns
t _{SCKF}	SCK fall time	Master	-	2.7	-	ns
t _{MIS}	MISO setup to SCK	Master	-	10	-	ns
t _{MIH}	MISO hold after SCK	Master	-	10	-	ns
t _{MOS}	MOSI setup to SCK	Master	-	0.5 × t _{SCK}	-	ns
t _{MOH}	MOSI hold after SCK	Master	-	1.0	-	ns
f _{SSCK}	Slave SCK clock frequency	Slave	-	-	5	MHz
t _{SSCK}	Slave SCK Period	Slave	6 × t_{CLK_PER}	-	-	ns
t _{SSCKW}	SCK high/low width	Slave	3 × t_{CLK_PER}	-	-	ns
t _{SSCKR}	SCK rise time	Slave	-	-	1600	ns
t _{SSCKF}	SCK fall time	Slave	-	-	1600	ns
t _{SIS}	MOSI setup to SCK	Slave	0.0	-	-	ns
t _{SIH}	MOSI hold after SCK	Slave	3 × t_{CLK_PER}	-	-	ns
t _{SSS}	SS setup to SCK	Slave	-	t_{CLK_PER}	-	ns
t _{SSH}	SS hold after SCK	Slave	-	t_{CLK_PER}	-	ns
t _{SOS}	MISO setup to SCK	Slave	-	8.0	-	ns
t _{SOH}	MISO hold after SCK	Slave	-	13	-	ns
t _{SOSS}	MISO setup after SS low	Slave	-	11	-	ns
t _{SOSH}	MISO hold after SS low	Slave	-	8.0	-	ns

3.5.4 Programming Time

A clarification of the *Programming Time* section has been made. *Table 32-26* has been upgraded from *Programming Times* to *Memory Programming Specifications* in the *Electrical Characteristics*. Functional change is shown in **bold**.

Table 32-26. Memory Programming Specifications

Symbol	Description	Min.	Typ. †	Max.	Unit	Conditions
Data EEPROM Memory Specifications						
E _{EE} *	Data EEPROM byte endurance	100k	—	—	Erase/Write cycles	-40°C ≤ T _A ≤ +105°C
t _{EE_RET}	Characteristic retention	—	40	—	Year	T _A = 55°C
t _{EE_PBC}	Page Buffer Clear (PBC)	—	7	—	CLK _{CPU} cycles	
t _{EE_EEER}	Full EEPROM Erase (EEER)	—	4	—	ms	
t _{EE_WP}	Page Write (WP)	—	2	—	ms	
t _{EE_ER}	Page Erase (ER)	—	2	—	ms	
t _{EE_ERWP}	Page Erase-Write (ERWP)	—	4	—	ms	
Program Flash Memory Specifications						
E _{FL} *	Flash memory cell endurance	10k	—	—	Erase/Write cycles	-40°C ≤ T _A ≤ +105°C
t _{FL_RET}	Characteristic retention	—	40	—	Year	T _A = 55°C
V _{FL_UPDI}	V _{DD} for Chip Erase operation	V _{BODLEVEL0} ⁽¹⁾	—	V _{DDMAX}	V	
t _{FL_PBC}	Page Buffer Clear (PBC)	—	7	—	CLK _{CPU} cycles	
t _{FL_CHER}	Chip Erase (CHER)	—	4	—	ms	
t _{FL_WP}	Page Write (WP)	—	2	—	ms	
t _{FL_ER}	Page Erase (ER)	—	2	—	ms	
t _{FL_ERWP}	Page Erase/Write (ERWP)	—	4	—	ms	
t _{FL_UPDI}	Chip Erase with UPDI	—	50	—	ms	4 KB Flash
		—	30	—	ms	2 KB Flash
† Data found in the “Typ.” column is at T _A = 25°C and V _{DD} = 3.0V unless otherwise specified. These parameters are not tested and are for design guidance only.						
* These parameters are characterized but not tested in production.						
Note:						
1. During Chip Erase, the Brown-out Detector (BOD) configured with BODLEVEL0 is forced ON. The erase attempt will fail if the supply voltage V _{DD} is below V _{BOD} for BODLEVEL0.						

3.6 Package Drawings

3.6.1 Package Marking Information

Package marking information is missing in the data sheet. This section contains all package marking information for:

ATtiny202/204/402/404/406 Automotive devices.

Figure 3-1. Package Marking Information

Rev. 30-009000A-AVR
11/02/2020

Legend:	XX...X	Customer-specific information or Microchip part number
	Y	Year code (last digit of calendar year)
	YY	Year code (last 2 digits of calendar year)
	WW	Week code (week of January 1 is week '01')
	NNN	Alphanumeric traceability code
	ⓔ3	Pb-free JEDEC [®] designator for Matte Tin (Sn)

Note: In the event the full Microchip part number cannot be marked on one line, it will be carried over to the next line, thus limiting the number of available characters for customer-specific information.

Figure 3-2. 8-Pin SOIC



Figure 3-3. 14-Pin SOIC




Figure 3-4. 20-Pin SOIC





Figure 3-5. 20-Pin VQFN



4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1 Revision History

Doc Rev.	Date	Comments
D	04/2024	- Document: - Editorial updates - Added new data sheet clarifications: - SPI: 3.4.1. SPI Clock - Electrical Characteristics: 3.5.1. Power Consumption. The Power Consumption in Power-Down (Max 25°C) reduced from 2 µA to 1.0 µA. 3.5.3. SPI - Timing Characteristics 3.5.4. Programming Time
C	08/2023	- Document: - Editorial updates - Silicon Errata Issues added: - Device: 2.2.2. Write Operation Lost if Consecutive Writes to Specific Address Spaces - NVMCTRL: 2.5.1. Wrong Reset Value of NVMCTRL.CTRLA Register - Silicon Errata Issues updated: - Device: 2.2.1. Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values - RTC: 2.7.1. Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler Counter - Added new data sheet clarification: - Electrical Characteristics: 3.5.2. I/O Pin Characteristics

.....continued

Doc Rev.	Date	Comments
B	04/2021	- Added silicon revision C - Added new errata: - Device: 2.2.1. Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values - ADC: 2.3.3. Pending Event Stuck When Disabling the ADC - CCL: 2.4.3. The CCL Must be Disabled to Change the Configuration of a Single LUT - TCA: 2.8.1. Restart Will Reset Counter Direction in NORMAL and FRQ Mode - TCB: 2.9.3. CCMP and CNT Registers Act as 16-Bit Registers in 8-Bit PWM Mode - USART: 2.10.3. Full Range Duty Cycle Not Supported When Validating LIN Sync Field 2.10.4. Open-Drain Mode Does Not Work When TXD is Configured as Output - Updated RTC erratum: 2.7.1. Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler Counter - Removed Device erratum: <i>The Temperature Sensor is Not Calibrated on Parts with Date Code 727, 728 and 1728 (Year 2017, Week 27/28)</i> - Added new data sheet clarification: - Memories: 3.1.1. Fuses - Factory Default Values - SLPCTRL: 3.2.1. Sleep Mode Activity Overview - USART: 3.3.1. TXDATA Buffer - Package Drawings: 3.6.1. Package Marking Information
A	12/2019	Initial document release

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure

that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, TimeCesium, TimeHub, TimePictra, TimeProvider, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, EyeOpen, GridTime, IdealBridge, IGaT, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, MarginLink, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mSiC, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICTail, Power MOS IV, Power MOS 7, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, Turing, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2024, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-4362-3

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com	Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880-3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100	Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Hod Hasharon Tel: 972-9-775-5100 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820