MICROCHIP PIC32MX330/350/370/430/450/470

PIC32MX330/350/370/430/450/470 Family Silicon Errata and Data Sheet Clarification

The PIC32MX330/350/370/430/450/470 family of devices that you have received conform functionally to the current Device Data Sheet (DS60001185**H**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in Table 1 through Table 4. The silicon issues are summarized in Table 5.

The errata described in this document will be addressed in future revisions of the PIC32MX330/350/370/430/450/470 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

Data Sheet clarifications and corrections (if applicable) start on page 14, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB[®] X IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

For example, to identify the silicon revision level using MPLAB X IDE in conjunction with a hardware debugger:

- Using the appropriate interface, connect the device to the hardware debugger.
- 2. Open an MPLAB X IDE project.
- 3. Configure the MPLAB X IDE project for the appropriate device and hardware debugger.
- 4. Select <u>Window > Dashboard</u>, and then click the **Refresh Debug Tool Status** icon ().
- The part number and the Device and Revision ID values appear in the **Output** window

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The Device and Revision ID values for the various PIC32MX330/350/370/430/450/470 silicon revisions are shown in Table 1 and Table 4.

TABLE 1: SILICON DEVREY VALUES FOR DEVICES WITH 64 KB FLASH MEMORY

Part Number	Flash Memory Size	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽¹⁾				
Part Number	(KB)	Device ID.	Α0	A1	В0		
PIC32MX330F064H	64	0x05600053		04			
PIC32MX330F064L	64	0x05601053	0.40		0xB		
PIC32MX430F064H	64	0x05602053	0x0	0x1	UXD		
PIC32MX430F064L	64	0x05603053	1				

Note 1: Refer to the "**Memory Organization**" and "**Special Features**" chapters in the current Device Data Sheet (DS60001185**H**) for detailed information on Device and Revision IDs for your specific device.

TABLE 2: SILICON DEVREV VALUES FOR DEVICES WITH 128 KB FLASH MEMORY

Part Number	Flash Memory	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽¹⁾					
Part Number	Size (KB)	Device ID.	Α0	A 1	В0	C0		
PIC32MX350F128H	128	0x0570C053			0x8			
PIC32MX350F128L	128	0x0570D053	0x0	0x1		0xD		
PIC32MX450F128H	128	0x0570E053	0.00			UXD		
PIC32MX450F128L	128	0x0570F053						

Note 1: Refer to the "Memory Organization" and "Special Features" chapters in the current Device Data Sheet (DS60001185H) for detailed information on Device and Revision IDs for your specific device.

TABLE 3: SILICON DEVREY VALUES FOR DEVICES WITH 256 KB FLASH MEMORY

Part Number	Flash Memory Size	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽¹⁾				
Part Number	(KB)	Device ib.	A0	A 1	B1		
PIC32MX350F256H	256	0x05704053		0x1			
PIC32MX350F256L	256	0x05705053	0x0		0xA		
PIC32MX450F256H	256	0x05706053	UXU		UXA		
PIC32MX450F256L	256	0x05707053					

Note 1: Refer to the "**Memory Organization**" and "**Special Features**" chapters in the current Device Data Sheet (DS60001185**H**) for detailed information on Device and Revision IDs for your specific device.

TABLE 4: SILICON DEVREV VALUES FOR DEVICES WITH 512 KB FLASH MEMORY

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽¹⁾				
		Α0	В0			
PIC32MX370F512H	0x05808053					
PIC32MX370F512L	0x05809053	0x0	0xC			
PIC32MX470F512H	0x0580A053	UXU	UXC			
PIC32MX470F512L	0x0580B053	1				

Note 1: Refer to the "**Memory Organization**" and "**Special Features**" chapters in the current Device Data Sheet (DS60001185**H**) for detailed information on Device and Revision IDs for your specific device.

TABLE 5: SILICON ISSUE SUMMARY

				Affe	cted	Rev	/isio	ns		
Module	Feature	Item #	Issue Summary	Flash Memory (KB)	A 0	A 1	B 0	B 1	C 0	
				64	Х	Х	Χ	_	_	
ADC	Differential	1.	The ADC module is not within the published data	128	Х	Х	Χ	_	Х	
ADC	Nonlinearity	 sheet specification when operating at a conversion rate above 500 ksps. 	256	Х	Х	_	Х	_		
				512	Х	_	Х	_	_	
				64	Х	Х	Χ	_	_	
Clask			A clock signal is present on the CLKO pin, regardless of the clock source and setting of the CLKO Enable	128	Χ	Χ	Χ	_	Х	
Clock	Clock Out	2.	Configuration bit, during a Power-on Reset (POR) condition.	256	Χ	Χ	_	Х	_	
	Condition.		512	Χ	_	X	_	_		
Reserved		3.	_	_	_		_		_	
				64	Χ	Χ	Χ	_	_	
I/O	1/0 1/0	4.	Port pin RF6 is not 5V tolerant. Use RF6 as a non-5V	128	Χ	Χ	Χ	_	Х	
1/0	1/0		tolerant pin only.	256	Х	Χ	_	Χ	_	
				512	Х	_	Χ	_	_	
					64	Х	Х	Χ	_	_
5V Tolerant	Dull upo	5.	Internal pull-up resistors may not guarantee a logical		Χ	Х	Χ	_	Х	
I/O Pins	Pull-ups	5.	'1' on digital inputs on 5V tolerant pins.	256	Χ	Χ	_	Х	_	
				512	Χ	_	X	_	_	
				64	Χ			_	_	
Non-5V Tolerant I/O	Dell		Internal pull-up resistors may not guarantee a logical	128	Х			_		
Pins	Pull-ups	6.	'1' on digital inputs on non-5V tolerant pins.	256	Χ		_		_	
				512		_		_	_	
				64	Х	Х	Χ	_	_	
.2 -			When the I ² C client receives any of the reserve	128	Х	Х	Χ	_	Х	
I ² C	Client Mode	7.	address with STRICT = 1, an ACK will be generated, but an interrupt will not be generated.	256	Х	Х	_	Х	_	
			- -	512	Х	_	Х	_	_	
				64	Х	Х	Х	_	_	
ITA C	Boundary			128	Х	Х	Х	_	Х	
JTAG	Scan	8.	Boundary Scan is not supported.	256	Х	Х	_	Х	_	
				512	Х	_	Х	_	_	
<u> </u>		<u> </u>		1						

Legend: An 'X' indicates the issue is present in this revision of the silicon.

Shaded cells with an Em dash ('—') indicate that this silicon revision does not exist for this issue. Blank cells indicate an issue has been corrected or does not exist in this revision of the silicon.

TABLE 5: SILICON ISSUE SUMMARY (CONTINUED)

				Affected Revisions							
Module	Feature	Item #	Issue Summary	Flash Memory (KB)	A 0	A 1	B 0	B 1	C 0		
				64	Χ	Χ	Χ	-	_		
Watchdog	Windowed	9.	Clearing the Watchdog Timer inside the window when	128	Х	Х	Χ	-	Х		
Timer	Watchdog	J.	in Window mode may cause a reset.	256	Х	Х	_	Χ	_		
				512	Х	_	Χ	_	_		
				64				_	_		
Debug	Debug Pins	10.	On-chip debug pins require special consideration.	128	Х	Χ	Χ	_	Х		
	Debug i iiis	10.	Cir-Cirip debug pina require special consideration.	256	Χ	Х	_	Χ	_		
				512		_		_	_		
				64	Χ	Χ	Χ	_	_		
USB Idle Interrupt	11.	USB Idle interrupts cease if the IDLEIF flag is cleared	128	Χ	Χ	Χ	-	Х			
	idie interrupt	11.	and the bus is left idle for more than 3 ms.	256	Χ	Χ	-	Χ	_		
				512	Х	_	Χ	-	_		
				64	Х	Х	Χ	-	_		
I/O Port	Open Drain	en Drain 12.	The Open Drain selection (ODCx) on I/O port pins is not available when the pin is configured for anything	128	Х	Х	Χ	-	Х		
I/O FOIL	Open Diam	12.	other than a standard port output.	256	Х	Х	-	Χ	_		
				512	Х	_	Χ	-	_		
				64				_	_		
Flash	Flash Memory	13.	The Program Write Protection (PWP) bits are not able to protect all 512 KB of Flash memory on	128				-			
Memory	i lasii wemory	13.	PIC32MX370/470 devices.	256			-		_		
				512	Х	_	Χ	_	_		
				64	Х	Х	Χ	_	_		
Timer1	Interrupts	14.	Under specific conditions, Timer1 will not generate	128	Х	Х	Χ	_	Х		
Timeri	interrupts	14.	interrupts.	256	Х	Х	_	Х	_		
				512	Х	_	Х	_	_		
				64	Х	Х	Χ	_			
UART	Auto-baud	45	The Automatic Baud Rate feature does not function to	128	Х	Х	Χ	_	Х		
UANT	Auto-Dauu	15.	set the baud rate.	256	Х	Х	_	Х			
				512	Х	_	Χ	_	_		

Legend: An 'X' indicates the issue is present in this revision of the silicon.

Shaded cells with an Em dash ('—') indicate that this silicon revision does not exist for this issue. Blank cells indicate an issue has been corrected or does not exist in this revision of the silicon.

TABLE 5: SILICON ISSUE SUMMARY (CONTINUED)

				Affe	cted	Rev	/isio	ns	
Module	Feature	Item #	Issue Summary	Flash Memory (KB)	A 0	A 1	B 0	B 1	C 0
				64	Χ	Χ	Χ	-	_
UART	Synchronizati	16.	On a RX FIFO overflow, shift registers stop receiving	128	Χ	Х	Х	_	Х
O/ (()	on	10.	data, which causes the UART to lose synchronization.	256	Χ	Χ	_	Χ	_
				512	Χ	_	Х	_	_
				64	Χ	Х	Х	_	_
CTMU	Module	17.	The CTMU module is not functional	128	Χ	Х	Х	_	Х
Operation		The OTIMe medale is not idinational	256	Χ	Χ	_	Χ	_	
				512	Χ	_	Х	_	_
				64	Χ	Х	Х	_	_
ADC	IVREF Sensing	18.	Testing the IVREF setting with the ADC module does	128	Χ	Х	Χ	_	Х
ABO	TVILL OCHSING		not function as intended.	256	Χ	Χ	_	Χ	_
				512	Χ	_	Х	_	_
				64	Χ	Х	Х	_	_
HVD	HVDR	19.	On power-up, the High-Voltage Detect Reset event	128	Χ	Х	Χ	_	Χ
1110	TIVEIC	10.	flag, RCON <hvdr> is being set.</hvdr>	256	Χ	Χ	_	Χ	_
				512	Χ	_	Х	_	_
				64	Χ	Х	Х	_	_
Power- Saving	ldle	20.	On exit from Sleep mode, the SLEEP and IDLE status	128	Χ	Х	Χ	_	Х
Modes	idle	20.	bits in the RCON register are being set.	256	Χ	Х	_	Χ	_
				512	Χ	_	Х	_	_
				64	Χ	Х	Х	_	_
Flash	Write	21.	When enabled, the Boot Write Protect (BWP) bit also protects and overlaps the first page of user program	128	Χ	Х	Х	_	Х
Memory	Protection	۷۱.	space below 0x1000 in addition to the boot segment	256	Х	Х	_	Χ	_
				512	Х	_	Х	_	_
				64	Х	Х	Х	_	_
Flash	Write	22.	The Program Write Protection (PWP) bit field is off by	128	Х	Х	Х	_	Х
Memory	Protection	22.	one page relative to the definition in the data sheet.	256	Х	Х	_	Χ	
I agend: A			a is present in this revision of the cilicon	512	Х	_	Х	_	_

Legend: An 'X' indicates the issue is present in this revision of the silicon.

Shaded cells with an Em dash ('—') indicate that this silicon revision does not exist for this issue. Blank cells indicate an issue has been corrected or does not exist in this revision of the silicon.

TABLE 5: SILICON ISSUE SUMMARY (CONTINUED)

				Affe	cted	Rev	/isio	ns	
Module	Feature	Item #	Issue Summary	Flash Memory (KB)	A 0	A 1	B 0	B 1	C 0
				64	Х	Χ	Х	_	_
Flash	Write	23.	The Program Write Protection (PWP) bits are not enabled unless the Boot Write Protect (BWP) bit is	128	Х	Χ	Х	_	Х
Memory Protection	20.	also enabled.	256	Х	Χ	_	Х	—	
			512	Х	_	Х	_	_	
I/O Pins Peripheral				64	Х	Х	Х	_	_
	Peripheral Pin		The RPF3 pin is not available for PPS functions on	128	Х	Х	Х	_	Х
I/O FIIIS	Select (PPS)	24.	USB devices.	256	Х	Х	_	Х	_
				512	Х	_	Х	_	_
				64	Х	Х	Х	_	_
USB Low- Speed	Low-Speed	25.	USB Low Speed DEVICE & HOST mode is not	128	Х	Х	Х	_	Х
Mode	Mode	25.	supported.	256	Х	Х	_	Х	_
				512	Х	_	Х	_	_
				64	Х	Х	Х	_	_
Flash:	RTSP	26.	RTSP of Configuration Words is not functional.	128	Х	Х	Х	_	Х
RTSP	KIOP	20.	Transition violes is not functional.	256	Х	Х	_	Х	_
				512	Х	_	Х	_	_

Legend: An 'X' indicates the issue is present in this revision of the silicon.

Shaded cells with an Em dash ('--') indicate that this silicon revision does not exist for this issue.

Blank cells indicate an issue has been corrected or does not exist in this revision of the silicon.

Silicon Errata Issues

- **Note 1:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. The table provided in each issue indicates which issues exist for a particular revision of silicon based on Flash memory size.
 - 2: The following applies to the Affected Silicon Revision tables in each silicon issue:
 - · An 'X' indicates the issue is present in this revision of silicon
 - · Shaded cells with an Em dash ('--') indicate that this silicon revision does not exist for this issue
 - · Blank cells indicate an issue has been corrected or does not exist in this revision of silicon.

1. Module: ADC

When the ADC is configured for 10-bit operation, the specifications in the data sheet are not met for operation above 500 ksps.

Work around

For 600 ksps operation, RIN = 500 ohms, TSAMP = 2 TAD. The module specifications are shown in Table 6. For 1000 ksps operation, RIN = 200 ohms, TSAMP = 2 TAD. The module specifications are shown in Table 7.

TABLE 6: 600 KSPS OPERATION

Parameter No.	Symbol	Minimum	Typical	Maximum	Units					
AD17	RIN	_	20		Ohm					
ADC Accuracy – I	Measurements take	en with External Ve	REF+/VREF-							
AD21c	INL	-1.5		1.5	LSB					
AD22c	DNL	-1.4	_	2.1	LSB					
AD23c	GERR	-1.2	-1.2 — 1.2		LSB					
ADC Accuracy – I	ADC Accuracy – Measurements taken with Internal VREF+/VREF-									
AD21d	INL	-1.5	_	1.5	LSB					
AD22d	DNL	-1.4	_	2.1	LSB					

TABLE 7: 1000 KSPS OPERATION

Parameter No.	Symbol	Minimum	Typical	Maximum	Units					
AD17	RIN	20		200	Ohm					
ADC Accuracy – Measurements taken with External VREF+/VREF-										
AD21c	INL	-5.2	_	6.5	LSB					
AD22c	DNL	-3.4	_	7	LSB					
AD23c	GERR	-1.5	_	1.5	LSB					
ADC Accuracy – I	Measurements take	en with Internal VR	EF+/VREF-							
AD21d	INL	-5.2	_	6.5	LSB					
AD22d	DNL	-3.4	-3.4 —		LSB					

Device Flash	Device Silicon Revision							
Memory (KB)	A0	A1	B0	B1	C0			
64	Х	Х	Χ	_	_			
128	Х	Х	Х	_	Χ			
256	Χ	Х	_	Χ	_			
512	Χ	_	Χ	_	_			

2. Module: Clock

A clock signal is present on the CLKO pin, regardless of the clock source and setting of the CLKO Enable Configuration bit, OSCIOFNC (DEVCFG1<10>), during a Power-on Reset (POR) condition.

Work around

Do not connect the CLKO pin to a device that would be adversely affected by rapid pin toggling or a frequency other than that defined by the oscillator configuration. Do not use the CLKO pin as an input if the device connected to the CLKO pin would be adversely affected by the pin driving a signal out.

Affected Silicon Revisions

Device Flash	Device Silicon Revision							
Memory (KB)	A0	A1	B0	B1	C0			
64	Χ	Χ	Χ	_	_			
128	Χ	Χ	Х	_	Χ			
256	Х	Х	_	Х	_			
512	Χ	_	Χ	_	_			

3. Module: Reserved

The issue, previously reported in a prior revision of this errata, is no longer relevant and was removed.

4. Module: I/O

The port pin, RF6, is not 5V tolerant. Use RF6 as a non-5V tolerant pin only.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Χ	_	_	
128	Χ	Х	Χ	_	Χ	
256	Х	Х	_	Х	_	
512	Χ	_	Х	_	_	

5. Module: 5V Tolerant I/O Pins

When internal pull-ups are enabled on 5V tolerant pins, the level as measured on the pin and available to external device inputs may not exceed the minimum value of VIH, and therefore qualify as a logic "high". However, with respect to the PIC32 device, as long as VDD \geq 3V and the load doesn't exceed -50 μA , the internal pull-ups are guaranteed to be recognized as a logic "high" internally to the device.

Work around

It is recommend to use only external pull ups:

- To guarantee a logic "high" for external logic input circuits outside of the PIC32 device
- For PIC32 device inputs, if the external load exceeds -50 μA or VDD < 3V

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Χ	_	_	
128	Х	Х	Х	_	Х	
256	Х	Х	_	Х	_	
512	Х	_	Х	_		

6. Module: Non-5V Tolerant I/O Pins

When internal pull-ups are enabled on non-5V tolerant pins, the level as measured on the pin and available to external device inputs may not exceed the minimum value of VIH, and therefore qualify as a logic "high". However, with respect to the PIC32 device, as long as VDD \geq 3V and the load doesn't exceed -50 μA , the internal pull ups are guaranteed to be recognized as a logic "high" internally to the device.

Work around

It is recommend to only use external pull ups:

- To guarantee a logic "high" for external logic input circuits outside of the PIC32 device
- For PIC32 device inputs, if the external load exceeds -50 μA or VDD < 3V

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ			_	_	
128	Χ			_		
256	Χ		_		_	
512		_		_		

7. Module: I²C

The client address, 0x78, is one of a group of reserved addresses. It is used as the upper byte of a 10-bit address when 10-bit addressing is enabled. The I²C module control register allows the programmer to enable both 10-bit addressing and strict enforcement of reserved addressing with the A10M and STRICT bits. When both bits are cleared, the device must respond to the reserved address 0x78, but it does not.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Х	_	_	
128	Х	Х	Χ	_	Χ	
256	Χ	Х	_	Х	_	
512	Х	_	Х	_	_	

8. Module: JTAG

Boundary Scan is not supported.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Χ	_	_	
128	Х	Х	Х	_	Х	
256	Χ	Х	_	Χ	_	
512	Х		Х	_	_	

9. Module: Watchdog Timer

When the Watchdog Timer module is used in Windowed mode, the module may issue a reset even if the user tries to clear the module within the allowed window.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Χ	_	_	
128	Х	Х	Х	_	Χ	
256	Х	Х	_	Х	_	
512	Х	_	Χ	_	_	

10. Module: Debug

For PIC32MX350/450 devices, the programming pin pairs at PGEC2/PGED2 and PGEC3/PGED3 may not function for on-chip debugging if the PGEC1 pin is open or is a logical "high".

Work arounds

 Use the PGEC1 and PGED1 pins for debugging.

Or

 Hold the PGEC1 pin to Vss with an external resistor with a value of 150k or less while debugging on another pair.

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	B0	B1	C0	
64				_	_	
128	Χ	Х	Χ	_	Χ	
256	Х	Х	_	Х	_	
512		_		_	_	

11. Module: USB

If the bus has been idle for more than 3 ms, the IDLEIF interrupt flag is set. If software clears the interrupt flag and the bus remains idle, the IDLEIF interrupt flag will not be set again.

Work around

Software can leave the IDLEIF bit set until it has received some indication of bus resumption (i.e., Resume, Reset, SOF, or Error).

Note:

Resume and Reset are the only interrupts that should be following IDLEIF assertion. If the IDLEIF bit is set, it should be okay to suspend the USB module (as long as this code is protected by the GUARD (USLPGRD bit (U1PWRC <4>)) and ACTPEND (UACTPND bit (U1PWRC <7>)) logic). This will require software to clear the IDLEIF interrupt enable bit to exit the USB ISR (if using interrupt driven code).

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Χ	_	_	
128	Χ	Х	Χ	_	Х	
256	Х	Х	_	Х	_	
512	Х	_	Х	_	_	

12. Module: I/O Port

The Open Drain selection (ODCx) on I/O port pins is not available when the pin is configured for anything other than a standard port output. In addition, the Open Drain feature is not available for dedicated or remappable Peripheral Pin Select (PPS) output features.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Х	_	_	
128	Х	Х	Х	_	Х	
256	Х	Х		Х	_	
512	Х	_	Х	_	_	

13. Module: Flash Memory

The Program Write Protection (PWP) bits are not able to protect all 512 KB of Flash memory on PIC32MX370/470 devices.

Work around

The PWP<7:0> bits in the DEVCFG0 Configuration register can protect a maximum of 508 KB of Flash memory.

Use a PWP<7:0> value of 0x10000000 for a maximum of 508 KB (memory location 0xBD07EFFF).

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64				_	_	
128				_		
256			_		_	
512	Х		Х			

14. Module: Timer1

Timer1 fails to generate interrupts when configured as follows:

- · External Clock Input and
- · Asynchronous Clock and
- Prescaler other than 1:1

Work around

Any other combination of the timer will generate interrupts as expected. For example, Synchronous mode or leaving the prescaler at 1:1.

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Х	_	_	
128	Χ	Х	Χ	_	Χ	
256	Χ	Х	_	Х	_	
512	Χ	_	Х	_	_	

15. Module: UART

The UART Automatic baud rate feature is intended to set the baud rate during run-time based on external data input. However, this feature does not function.

Work around

None.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Χ	_	_	
128	Х	Х	Χ	_	Χ	
256	Х	Х	_	Х	_	
512	Χ	_	Χ	_	_	

16. Module: UART

During a RX FIFO overflow condition, the shift register stops receiving data. This causes the UART to lose synchronization with the serial data stream. The only way to recover from this is to turn the UART OFF and ON until it synchronizes. This could require several OFF/ON sequences.

Work arounds

Work around 1:

Avoid the RX overrun condition by ensuring that the UARTx module has a high enough interrupt priority such that other peripheral interrupt processing latencies do not exceed the time to overrun the UART RX buffer based on the application baud rate. Alternately or in addition to, set the URXISEL bits in the UxSTA register to generate an earlier RX interrupt based on RX FIFO fill status to buy more time for interrupt latency processing requirements.

Work around 2:

If avoiding RX FIFO overruns is not possible, implement a ACK/NAK software handshake protocol to repeat lost packet transfers after restoring UART synchronization.

Affected Silicon Revisions

Device Flash	Device Silicon Revision					
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Х	-	_	
128	Χ	Х	Х	_	Х	
256	Χ	Х	_	Χ	_	
512	Х	_	Х	_	_	

17. Module: CTMU

The CTMU module is not functional.

Work around

None.

Affected Silicon Revisions

Device Flash		Device Silicon Revision				
Memory (KB)	A0 A1 B0 B1 C0					
64	Χ	Х	Χ	_	_	
128	Χ	Х	Χ	_	Χ	
256	Χ	Х	_	Χ	_	
512	Χ	_	Х	_	_	

18. Module: ADC

Converting the Internal Band Gap (IVREF) voltage source generates a High-Voltage Detect (HVD) event and aborts the conversion; therefore, this feature is not functional.

Work around

None.

Affected Silicon Revisions

Device Flash		Devic	e Silic	con Revision			
Memory (KB)	A0 A1 B0 B1 C0						
64	Χ	Х	Χ	_	_		
128	Χ	Х	Χ	_	Χ		
256	Χ	Х	_	Χ	_		
512	Х	_	Χ	_	_		

19. Module: HVD

On power-up, the High-Voltage Detect Reset, event flag, RCONRCONHVDR>, is set incorrectly.

On a power-up, only the POR, BOR, and EXTR bits should be set with the proper VCAP bypass capacitor value, as stated in the current data sheet.

Work around

Check the status of the POR bit in the RCON register when checking the HVDR bit. If the POR bit is set, both bits can be cleared as the HVDR bit is a false detection. If the POR bit is clear, the HVDR bit has been correctly detected and can be handled according to the requirements of the application.

Device Flash		Device Silicon Revision				
Memory (KB)	A0 A1 B0 B1 C0					
64	Χ	Х	Χ	_	_	
128	Χ	Х	Χ	_	Χ	
256	Х	Х	_	Х	_	
512	Χ	_	Χ	_	_	

20. Module: Power-Saving Modes

On exit from Sleep mode, both the SLEEP and IDLE status bits in the RCON register are set.

Work around

Add the following code to the user application at the point it wakes from Sleep mode:

```
rcon_var1 = RCON;
// ... enter Sleep mode
if (rcon_var1 & 0x4) Nop();
// If IDLE bit already set previously
// before sleep do nothing
else RCONbits.IDLE = 0x0;
// If IDLE bit is not set previously
// and is after Sleep mode then clear
```

Affected Silicon Revisions

Device Flash		Devic	evice Silicon Revision			
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Χ	_	_	
128	Х	Х	Χ	_	Х	
256	Х	Х	_	Χ	_	
512	Х	_	Χ	_	_	

21. Module: Flash Memory

When enabled, the Boot Write Protect (BWP) bit inadvertently also protects and overlaps the first page of PWP user program space below 0x1000, (i.e., PWP<7:0> = 0xFE), in addition to the boot segment, regardless of the state of the Program Write Protection (PWP) bits (DEVCFG0<19:12>). If BWP is enabled by setting the BWP bit (DEVCFG0<24>) = 0, users cannot Page Erase or program the first page of the PWP user program space. Only user run-time Page Erase or Program operations are affected, which does not include a Bulk erase of the entire Flash.

Work around

None. Refer to silicon issues 22 and 23 for related information

Affected Silicon Revisions

Device Flash		Devic	e Silic	on Re	evision			
Memory (KB)	A0 A1 B0 B1 C0							
64	Х	Х	Χ	_	_			
128	Х	Х	Χ	_	Χ			
256	Х	Х	_	Χ	_			
512	Х	_	Χ	_	_			

22. Module: Flash Memory

The Program Write Protection (PWP) bit field is off by one page relative to the data sheet definition. In silicon, PWP<7:0> = (n + 1), where 'n' is the DEVCFG0<19:12> value as defined in the data sheet.

TABLE 8: PWP BITS (DEVCFG0<19:12>)

Value	Expected	Actual		
11111111	Disabled	Disabled		
11111110	Memory below 0x01000 is write protected	Disabled		
11111101	Memory below 0x02000 is write protected	Memory below 0x01000 is write protected		
01111111	Memory below 0x80000 is write protected	Memory below 0x7F000 is write protected		

Work around

Set the PWP<7:0> bits (DEVCFG0<19:12>) = (DEVCFG0<PWP> - 1) to correct for the first page protection offset. Please refer to silicon issues 21 and 23 for related information.

Device Flash		Devic	e Silic	on Re	vision			
Memory (KB)	A0 A1 B0 B1 C0							
64	Х	Х	Х	_	_			
128	Χ	Х	Х	_	Χ			
256	Χ	Х	_	Χ	_			
512	Χ	_	Х	_	_			

23. Module: Flash Memory

The Program Write Protection (PWP) bits (DEVCFG0<19:12>) are not enabled unless the Boot Write Protect (BWP) bit (DEVCFG0<24> is also enabled (i.e., = 0).

Work around

None. Please refer to silicon issues 21 and 22 for related information.

Affected Silicon Revisions

Device Flash		Device Silicon Revision				
Memory (KB)	A0	A1	В0	B1	C0	
64	Χ	Х	Χ	_	_	
128	Χ	Х	Х	_	Х	
256	Χ	Х	_	Х	_	
512	Χ	_	Χ	_	_	

24. Module: I/O Pins

The RPF3 Peripheral Pin Select (PPS) functions are not available on PIN32MX4xx USB device variants. The PIC32MX3xx General Purpose devices are not affected.

Work around

None.

Affected Silicon Revisions

Device Flash		Devic	e Silic	on Re	vision			
Memory (KB)	A0	A1	В0	B1	C0			
64	Χ	Х	Х	_	_			
128	Χ	Х	Χ	_	Χ			
256	Χ	Х	_	Х	_			
512	Х	_	Х	_				

25. Module: USB Low-Speed Mode

USB Low-Speed mode is not functional in both DEVICE and HOST modes due to signal integrity compliance issues.

Work around

None.

Affected Silicon Revisions

Device Flash		Device Silicon Revision				
Memory (KB)	A0	A1	В0	B1	C0	
64	Х	Х	Χ	_	_	
128	Х	Х	Χ	_	Χ	
256	Х	Х	_	Χ	_	
512	Х	_	Χ	_	_	

26. Module: Flash: RTSP

Real-Time Serial Programming (RTSP) of Configuration Words is not functional.

Work around

None.

Device Flash		Devic	e Silic	con Revision			
Memory (KB)	A0 A1 B0 B1 C0						
64	Χ	Х	Χ	_	_		
128	Χ	Х	Χ	_	Χ		
256	Χ	Х	_	Х	_		
512	Χ	_	Χ	_	_		

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS60001185**H**):

No clarifications to report at this time.

APPENDIX A: REVISION HISTORY

Rev A Document (4/2013)

Initial release of this document; issued for revision A0 silicon.

Includes silicon issues 1 (ADC), 2 (Clock), 3 (Reserved), 4 (I/O), 5 (5V Tolerant I/O Pins), 6 (Non-5V Tolerant I/O Pins), 7 (I²C), 8 (JTAG), and 9 (Watchdog Timer).

Rev B Document (6/2013)

Updated the silicon revision to Rev. A1 and added the PIC32MX350/430/450 devices.

Added silicon issues 10 (Debug), 11 (USB), and 12 (I/O Port). Updated silicon issue 3 (Reserved).

Rev C Document (10/2013)

Added the 512 KB Flash memory devices (PIC32MX370/470).

Updated silicon issue 1 (ADC).

Added silicon issues 13 (Flash Memory) and 14 (Timer1).

Rev D Document (6/2014)

Added Data Sheet Clarification 1 (Packaging) and 2 (Power-Down Current (IPD)).

Rev E Document (2/2015)

The document was updated for silicon revision B0 devices:

- 128 KB devices were moved from Table 1 to Table 2.
- Added separate 128 KB row to Affected Silicon Revisions tables.

Added silicon issues 15 (UART), 16 (UART), 17 (CTMU), 18 (ADC), 19 (HVD), and 20 (Power-Saving Modes), 21 (Flash Memory), 22 (Flash Memory), and 23 (Flash Memory).

Deleted silicon issue 3 (CTMU).

Rev F Document (6/2015)

Deleted Data Sheet Clarification 1 (Packaging).

Added Data Sheet Clarification 1 (Power-Down Current (IPD)).

Updated Table 31-7.

Rev G Document (6/2018)

Added issue 24 (I/O Pins).

Removed Data Sheet Clarification 1 (Power-Down Current IPD).

Added **TABLE 3: "Silicon DEVREV Values For Devices With 256 KB Flash Memory**" to reflect updates for the 256 Flash Memory.

Rev H Document (01/2020

Updated B0 data for all errata.

Added a new silicon issue **25. Module: "USB Low-Speed Mode"**.

Rev J Document (11/2020)

Added silicon revision C0 for all errata.

Updated the verbiage of silicon Issue 7. Module: " I^{2C} " replacing the term "slave" with "client."

Updated the verbiage of Silicon Issue **25. Module:** "USB Low-Speed Mode".

Rev K Document (10/2022)

The following updates were performed in this revision.

- The note was clarified in silicon issue 11. Module: "USB"
- Added silicon issue 26. Module: "Flash: RTSP"

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not
 mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to
 continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at https://www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach. Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2013-2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-1397-8



Worldwide Sales and Service

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200

Fax: 480-792-7200 Fax: 480-792-7277 Technical Support:

http://www.microchip.com/ support

Web Address:

www.microchip.com

Atlanta Duluth, GA

Tel: 678-957-9614 Fax: 678-957-1455

Austin, TX Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL

Tel: 630-285-0071 Fax: 630-285-0075

Dallas Addison, TX

Tel: 972-818-7423 Fax: 972-818-2924

Detroit Novi, MI

Tel: 248-848-4000

Houston, TX Tel: 281-894-5983

Indianapolis
Noblesville, IN

Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800

Raleigh, NC Tel: 919-844-7510

New York, NY Tel: 631-435-6000

San Jose, CA Tel: 408-735-9110

Tel: 408-436-4270 **Canada - Toronto** Tel: 905-695-1980

Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney Tel: 61-2-9868-6733

China - Beijing Tel: 86-10-8569-7000

China - Chengdu Tel: 86-28-8665-5511

China - Chongqing Tel: 86-23-8980-9588

China - Dongguan Tel: 86-769-8702-9880

China - Guangzhou Tel: 86-20-8755-8029

China - Hangzhou Tel: 86-571-8792-8115

China - Hong Kong SAR Tel: 852-2943-5100

China - Nanjing Tel: 86-25-8473-2460

China - Qingdao Tel: 86-532-8502-7355

China - Shanghai Tel: 86-21-3326-8000

China - Shenyang Tel: 86-24-2334-2829

China - Shenzhen Tel: 86-755-8864-2200

China - Suzhou Tel: 86-186-6233-1526

China - Wuhan

Tel: 86-27-5980-5300 China - Xian

Tel: 86-29-8833-7252 China - Xiamen

Tel: 86-592-2388138 **China - Zhuhai** Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore Tel: 91-80-3090-4444

India - New Delhi Tel: 91-11-4160-8631

India - Pune Tel: 91-20-4121-0141

Japan - Osaka

Tel: 81-6-6152-7160

Japan - Tokyo

Tel: 81-3-6880- 3770

Korea - Daegu Tel: 82-53-744-4301

Korea - Seoul Tel: 82-2-554-7200

Malaysia - Kuala Lumpur Tel: 60-3-7651-7906

Malaysia - Penang Tel: 60-4-227-8870

Philippines - Manila Tel: 63-2-634-9065

Singapore Tel: 65-6334-8870

Taiwan - Hsin Chu Tel: 886-3-577-8366

Taiwan - Kaohsiung Tel: 886-7-213-7830

Taiwan - Taipei Tel: 886-2-2508-8600

Thailand - Bangkok Tel: 66-2-694-1351

Vietnam - Ho Chi Minh Tel: 84-28-5448-2100

EUROPE

Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829

Finland - Espoo Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching Tel: 49-8931-9700

Germany - Haan Tel: 49-2129-3766400

Germany - Heilbronn Tel: 49-7131-72400

Germany - Karlsruhe Tel: 49-721-625370

Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Germany - Rosenheim Tel: 49-8031-354-560

Israel - Ra'anana Tel: 972-9-744-7705

Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781

Italy - Padova Tel: 39-049-7625286

Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340

Norway - Trondheim Tel: 47-7288-4388

Poland - Warsaw Tel: 48-22-3325737

Romania - Bucharest Tel: 40-21-407-87-50

Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

Sweden - Gothenberg Tel: 46-31-704-60-40

Sweden - Stockholm Tel: 46-8-5090-4654

UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820