

KSZ879x/KSZ877x/KSZ876x Silicon Errata and Data Sheet Clarification

This document describes known silicon errata for the Microchip KSZ879x/KSZ877x/KSZ876x Ethernet switches, which include the following devices:


- KSZ8795CLXCC / KSZ8795CLXIC
- KSZ8794CNXCC / KSZ8794CNXIC
- KSZ8775CLXCC / KSZ8775CLXIC
- KSZ8765CLXCC / KSZ8765CLXIC

The silicon errata discussed in this document are for silicon revisions as listed in [Table 1](#). The silicon revision can be determined by the device's top marking as indicated in [Figure 1](#). A summary of KSZ879x/KSZ877x/KSZ876x silicon errata is provided in [Table 2](#).

TABLE 1: AFFECTED SILICON REVISIONS

Part Numbers	Silicon Revision
KSZ8795CLXCC, KSZ8795CLXIC, KSZ8794CNXCC, KSZ8794CNXIC, KSZ8775CLXCC, KSZ8775CLXIC, KSZ8765CLXCC, KSZ8765CLXIC	A2 and older

FIGURE 1: TOP MARKING DATE CODE INDICATION



Note: The purpose of [Figure 1](#) is to detail the top markings of an example part and highlight the location of the date code. Other top marking values may differ (lot codes, location of manufacture, etc.).

TABLE 2: SILICON ISSUE SUMMARY

Item Number	Silicon Issue Summary
1.	Transmission errors in 100BASE-TX Mode when Auto-Negotiation is disabled
2.	Link drops with some EEE link partners
3.	Establishing a link through low loss connections
4.	Idle transmitter common mode voltage drift at cold temperature
5.	Transmission halt with late collisions

Silicon Errata Issues

Module 1: Transmission errors in 100BASE-TX Mode when Auto-Negotiation is disabled

DESCRIPTION

When a PHY port is configured to disable Auto-Negotiation (AN) and forced to 100BASE-TX full/half-duplex mode, transmission errors may be output from the egress port.

END USER IMPLICATIONS

When this issue occurs, transmitted errors output from egress port may result in an unstable link with the partner.

Only PHY ports (Ports 1 to 4 for the KSZ8765/KSZ8775/KSZ8795, ports 1 to 3 for the KSZ8794) are affected by this issue. The Gigabit MAC processor port is unaffected. Additionally, PHY ports will not exhibit this issue if configured to Auto-Negotiation mode or forced to 10BASE-T mode.

Work Around

This issue can be prevented by using the appropriate script below when setting the port to force 100BASE-TX link (full-duplex) mode:

- Auto-MDI/MDIX Mode:

```
w nd 40 //Disable TX by writing 40h register NDh
w n9 00 //Set to Auto-MDI/MDIX by writing 00h to register N9h
w nc ff //Force 100 FD mode (disable AN)by writing FFh to register NCh
w nd 00 //Enable TX by writing 00h to register NDh
```

- Force-MDI Mode:

```
w nd 44 //Disable TX and Force to MDI by writing 44h to register NCh
w nc ff //Force 100 FD mode (disable AN) by writing FFh to register NCh
w nd 04 //Enable TX by writing 04h to regsiteer NDh
```

- Force-MDIX Mode:

```
w nd 46 //Disable TX and Force to MDIX by writing 46h to register NDh
w nc ff //Force 100 FD mode (disable AN) by writing FFh to register NCh
w nd 06 //Enable TX by writing 06h to register NDh
```

In the scripts above, “n” is the Port value 1,2,3 or 4. For example, to disable TX on Port 3: w 3d 40.

If the force 100BASE-TX half-duplex mode is required, then write 'df' instead of 'ff' to register nc.

For example, on port 3: w 3c df.

PLAN

This errata will not be corrected in a future revision.

Module 2: Link drops with some EEE link partners

DESCRIPTION

An issue with the EEE next page exchange between the KSZ879x/KSZ877x/KSZ876x and some EEE link partners may result in the link dropping.

END USER IMPLICATIONS

With certain EEE link partners, the KSZ879x/KSZ877x/KSZ876x may inadvertently drop the link between devices.

Work Around

Disable the EEE next page exchange in EEE Global Register 2 (0x35) by setting bits [3:0] to 0x0 (bits [3:0] default to 0xF).

PLAN

This errata will not be corrected in a future revision.

Module 3: Establishing a link through low loss connections

DESCRIPTION

The receiver of the embedded PHYs is tuned by default to support long cable length applications. This was developed using low quality, high loss cables. Because of this, the equalizer in the PHY may amplify high amplitude receiver signals to the point that the signal is distorted internally, preventing a link from being established.

END USER IMPLICATIONS

When connecting the PHY ports to link partners through low loss connections, the port may take a long time to establish a link, or may not link at all. This includes standard unshielded twisted pair cables less than 5m, capacitive coupled connections between two chips on the same PCB, or custom cables with low impedance loading.

Work Around 1

A more balanced receiver setting has been found that still functions at the long cable lengths and also supports low loss applications. To change this setting, write to the following registers:

```
w 6e a0 //Write A0h to register 6Eh to set up an indirect register write
w 6f 3c //Write 3Ch to register 6Fh to set the indirect register address to 3Ch
w a0 15 //Write 15h to the PHY equalizer register
```

Note: All PHYs are impacted by this new setting, the change is not PHY specific.

Work Around 2

If work around 1 does not solve the short cable issue in a CAT-5E or CAT-6 application, change the work around 1 register (0x3C) to its default value (0x0A), and use the following settings:

```
w 6e a0 //Write A0h to register 6Eh to set up an indirect register write
w 6f 4c //Write 4Ch to register 6Fh to set the indirect register address to 4Ch
w a0 40 //Write 40h to the indirect register 4Ch, the default value is 00h
```

PLAN

This errata will not be corrected in a future revision.

Module 4: Idle transmitter common mode voltage drift at cold temperature

DESCRIPTION

Below 0°C, the voltage controlled output of the transmitter, when inactive, can become unstable and affect the receiver of the link partner. This voltage instability is only observed when the transmitter is in a low activity state, such as auto-negotiation and 10Base-T idle conditions.

END USER IMPLICATIONS

This errata can manifest in long delays for the port to establish a link at cold temperatures, as well as errors when connected with a 10Base-T connection.

Work Around

If the transmitter is always actively driving the voltage levels, the cold temperature instability does not occur. The transmitters can be permanently enabled by executing the following commands:

```
w 6e a0 //Write A0h to register 6Eh to set up an indirect register write
w 6f 4e //Write 4Eh to register 6Fh to set the indirect register address to 4Eh
w a0 40 //Write 40h to enable the transmitter to actively transmit at all times
```

This workaround will increase the VDDAT current in auto-negotiation mode and 10Base-T Idle mode by ~60mA, but it will not increase the maximum current draw of the device at full traffic.

Note: All PHYs are impacted by this new setting, the change is not PHY specific.

PLAN

This errata will not be corrected in a future revision.

Module 5: Transmission halt with late collisions

DESCRIPTION

Section 4 of the IEEE 802.3 Specification details Carrier Sense Multiple Access / Collision Detection (CSMA/CD) parameters when operating in half-duplex mode. The first 512 bit times are designated as the slotTime, which is the maximum amount of time allowed for a collision to occur. If a link partner is configured incorrectly, where the PHY is linking in half-duplex mode but the MAC is configured in full-duplex mode, there is a chance that the link partner will generate a collision after the first 512 bit times, violating the IEEE 802.3 specification. These late collisions, combined with other factors, can cause the switch port transmitter to lock up and stop sending packets. The receiver will still function.

END USER IMPLICATIONS

If this erratum occurs, the switch will stop transmitting data to the half-duplex port, making it seem the half-duplex link partner has stopped communicating to the network. The more traffic there is, the greater the risk of the violating link partner generating a late collision that will affect the port.

Work Around

Ideally, the link partner that is violating the specification would need to be updated so the MAC and PHY are correctly configured to the same duplex setting. If the link partner cannot be modified to conform to the IEEE 802.3 specification, the switch can be re-configured to full-duplex when late collisions are detected to avoid a lock up condition. Of note, each switch port functions independently. Therefore, any work around must be implemented separately for each port.

Method 1:

To avoid transmitter lock up, when a port is linked in half-duplex mode, the software should monitor the TxLateCollision MIB counter (MIB Offset 0x16). If the number is ever non-zero, the software should force the link to function in full-duplex mode by disabling auto-negotiation and setting full-duplex and the appropriate speed in the Port Control 9 Registers (addresses 0x1C, 0x2C, etc.)

Method 2:

To detect transmitter lock up, the software should monitor the Port x Tx Total Bytes and the Port x Rx Total Bytes. If the Port x Rx Total Bytes is incrementing but the Port x Tx Total Bytes remains the same, the software should perform a hard reset of the switch.

PLAN

This erratum will not be corrected in a future revision.

APPENDIX A: DOCUMENT REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS80000687C (08-03-18)	Module 5.	Added new erratum for Transmission halt with late collisions
	Module 3.	Updated to add additional second work around method. Changed length of cable in end user implications to 5m.
DS80000687B (11-21-17)	Modules 3. and 4.	Added modules 3 and 4
DS80000687A (01-06-16)	All	Initial release

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: <http://microchip.com/support>

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Helder, JukeBlox, KeeLoq, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntellIMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 9781522436003

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
= ISO/TS 16949 =

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-67-3636

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820