

PIC18F66K80 Family Silicon Errata and Data Sheet Clarification

The PIC18F66K80 family devices that you have received conform functionally to the current Device Data Sheet (DS30009977G), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC18F66K80 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A6**).

Data Sheet clarifications and corrections start on [page 10](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate website (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select Programmer > Reconnect.
 - b) For MPLAB X IDE, select Window > Dashboard and click the Refresh Debug Tool Status icon ().
5. Depending on the development tool used, the part number and Device Revision ID value appear in the Output window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC18F66K80 silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾			
		A2	A3	A4	A6
PIC18F66K80	60E0	2h	3h	4h	6h
PIC18F65K80	6140				
PIC18F46K80	6100				
PIC18F45K80	6160				
PIC18F26K80	6120				
PIC18F25K80	6180				
PIC18LF66K80	61C0				
PIC18LF65K80	6220				
PIC18LF46K80	61E0				
PIC18LF45K80	6240				
PIC18LF26K80	6200				
PIC18LF25K80	6260				

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of Configuration memory space. They are shown in hexadecimal in the format, "DEVID DEVREV".

2: Refer to the "PIC18FXXK80 Family Flash Microcontroller Programming Specification" (DS39972) for detailed information on Device and Revision IDs for your specific device.

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾			
				A2	A3	A4	A6
Analog-to-Digital Converter (A/D)	A/D Performance	1.	The 12-bit A/D performance is outside the data sheet's A/D Converter specifications.	X	X	X	X
EUSART	Synchronous Transmit	2.	When using the Synchronous Transmit mode, transmitted data may become corrupted if using the TXxIF bit to determine when to load the TXREGx register.	X			
ECCP	Auto-Shutdown	3.	The tri-state setting of the auto-shutdown feature in the enhanced PWM will not successfully drive the pin to tri-state.	X	X	X	X
ECAN	CAN Clock Source Selection	4.	The CLKSEL bit in the CIOCON register is modifiable while the ECAN module is active.	X			
Ultra Low-Power Sleep	Sleep Entry	5.	Entering Ultra Low-Power Sleep mode by setting RETEN = 0 and SRETEN = 1, will cause the part to not be programmable through ICSP™.	X			
IPD and IDD	Maximum Limit	6.	Maximum current limits may be higher than specified in Table 31-2 of the data sheet.	X			
Reset (BOR)	Enable/Disable	7.	An unexpected Reset may occur if the Brown-out Reset module (BOR) is disabled and then re-enabled, when the High/Low-Voltage Detection module (HLVD) is not enabled (HLVDCON<4> = 0).	X	X	X	X
ECAN	EWIN	8.	The enhanced window address feature, EWIN<4:0>, in the ECANCON register, will not move the BnCON 0≤n≤5 registers into the access window of RAM.	X			
MCLRE	Master Clear Enable	9.	The Master Clear pin will not be readable when MCLRE is set to off for all 28-pin part variants (PIC18F2XK80).	X	X	X	X
Timer1/Timer3	Gated Enable	10.	Timer1 and Timer3 gate control will not function up to the speed of Fosc when the TxCON is set to the system clock (TxCON<7:6> = 01).	X	X		
Timer1/Timer3	Interrupt	11.	When the timer is operated in Asynchronous External Input mode, unexpected interrupt flag generation may occur.	X	X	X	X
Primary Oscillator	XT Mode	12.	XT Primary Oscillator mode does not reliably function when the driving crystals are above 3 MHz.	X	X	X	
ECAN	Disable/Sleep mode	13.	Disable/Sleep mode reverts CANTX control to TRISx/LATx instead of going to Recessive state.	X	X	X	X
ECAN	CLKSEL bit	14.	Setting CLKSEL bit of CIOCON can occasionally lead to missed incoming CAN messages.	X	X	X	X
EUSART	Receive Interrupt	15.	Unintended double execution of CALL instruction.	X	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A6**).

1. Module: Analog-to-Digital Converter (A/D)

The 12-bit A/D performance is outside the data sheet's A/D Converter specifications. When used as a 12-bit A/D, the possible issues are: high offset error, up to a maximum of ± 25 LSBs at 25°C, ± 30 LSBs at 85°C, 125°C and -40°C; high DNL error, up to a maximum of +6.0/-4.0 LSBs; and multiple missing codes, up to a maximum of twenty. Users should evaluate the 12-bit A/D performance in their application using the suggested work around below. See [Table 3](#) for guidance specifications.

The 12-bit A/D issues will be fixed in future revisions of this part. Reduced bit resolution specifications can be derived by dividing, as appropriate. For instance, 10-bit guidance is obtained by dividing the parameters in [Table 3](#) by four.

A/D Offset

The A/D may have high offset error, up to a maximum of ± 25 LSBs; it can be used if the A/D is calibrated for the offset.

Work around

Calibrate for offset in Single-Ended mode by connecting A/D +ve input to ground and taking the A/D reading. This will be the offset of the device and can be used to compensate for the subsequent A/D readings on the actual inputs.

TABLE 3: A/D CONVERTER CHARACTERISTICS

Param No.	Sym.	Characteristic	Min.	Typ.	Max.	Units	Conditions
A01	NR	Resolution	—	—	12	bit	$\Delta V_{REF} \geq 5.0V$
A03	EIL	Integral Linearity Error	—	—	± 10.0	LSb	$\Delta V_{REF} \geq 5.0V$
A04	EDL	Differential Linearity Error	—	—	+6.0/-4.0	LSb	$\Delta V_{REF} \geq 5.0V$
A06	EOFF	Offset Error	—	—	± 25 ± 30	LSb	$\Delta V_{REF} \geq 5.0V$, TEMP = 25°C TEMP $\geq 85^\circ C$, -40°C
A07	EGN	Gain Error	—	—	± 15	LSb	$\Delta V_{REF} \geq 5.0V$
A10	—	Monotonicity ⁽¹⁾	—				$V_{SS} \leq V_{AIN} \leq V_{REF}$
A20	ΔV_{REF}	Reference Voltage Range ($V_{REFH} - V_{REFL}$)	3	—	$AV_{DD} - AV_{SS}$	V	
A21	V_{REFH}	Reference Voltage High	$AV_{SS} + 3.0V$	—	$AV_{DD} + 0.3V$	V	
A22	V_{REFL}	Reference Voltage Low	$AV_{SS} - 0.3V$	—	$AV_{DD} - 3.0V$	V	
A25	V_{AIN}	Analog Input Voltage	V_{REFL}	—	V_{REFH}	V	

Note 1: The A/D conversion result never decreases with an increase in the input voltage.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

2. Module: EUSART

In Synchronous Transmit mode, data may be corrupted if using the TXxIF bit to determine when to load the TXREGx register. One or more of the intended transmit messages may be incorrect.

Work around

A fixed delay added before loading TXREGx may not be a reliable work around. When loading the TXREGx, check that the TRMT bit inside of the TXSTAx register is set instead of checking the TXxIF bit. The following code can be used:

```
while(!TXSTAxbits.TRMT);
// wait to load TXREGx until TRMT is set
```

Affected Silicon Revisions

A2	A3	A4	A6				
X							

3. Module: ECCP

The tri-state setting of the auto-shutdown feature, in the enhanced PWM will not successfully drive the pin to tri-state. The pin will remain an output and should not be driven externally. All tri-state settings will be affected.

Work around

Use one of the other two auto-shutdown states available, as outlined in the data sheet.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

4. Module: ECAN

The CLKSEL bit in the CIOCON register remains modifiable while the ECAN module is not in Configuration mode. Accidental state changes of this bit will result in immediate bit clock changes that will affect all nodes on the bus.

Work around

While the ECAN module is in Run mode, do not modify the state of the CLKSEL bit in the CIOCON register unless the CAN module is first changed into Configuration mode.

Affected Silicon Revisions

A2	A3	A4	A6				
X							

5. Module: Ultra Low-Power Sleep

Entering Ultra Low-Power Sleep mode by setting RETEN = 0 and SRETEN = 1 will cause the part to not be programmable through ICSP™. This issue occurs when the RETEN fuse bit in CONFIG1L<0> is cleared to '0', the SRETEN bit in the WDTCON register is set to '1' and a SLEEP instruction is executed within the first 350 μs of code execution. This happens after a Reset event, causing the part to enter Ultra Low-Power Sleep mode.

Work around

Use Normal Sleep and Low-Power Sleep modes only, or on any Reset, ensure that at least 350 μs pass before executing a SLEEP instruction when ULP is enabled. To ensure the Ultra Low-Power Sleep mode is not enabled, the RETEN fuse bit in CONFIG1L<0> should be set to a '1' and the SRETEN bit in the WDTCON register should be cleared to a '0'. The following code can be used:

```
//This will ensure the RETEN fuse is set to 1
#pragma config RETEN = OFF
//This will ensure the SRETEN bit is 0
WDTCONbits.SRETEN = 0;
```

If the Ultra Low-Power Sleep mode is needed, then the user must ensure that the minimum time, before the first SLEEP instruction is executed, is greater than 350 μs.

Affected Silicon Revisions

A2	A3	A4	A6				
X							

6. Module: IPD and IDD

The IPD and IDD limits do not match the data sheet. The IPD values, shown in **bold** in [Section 31.2 “DC Characteristics: Power-Down and Supply Current PIC18F66K80 Family \(Industrial/Extended\)”](#) (below), reflect the updated silicon maximum limits.

All IDD maximum limits will equal 2.8 times the value listed in the data sheet.

Affected Silicon Revisions

A2	A3	A4	A6				
X							

31.2 DC Characteristics: Power-Down and Supply Current PIC18F66K80 Family (Industrial/Extended)

PIC18F66K80 (Industrial/Extended)		Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial $-40^{\circ}\text{C} \leq T_A \leq +125^{\circ}\text{C}$ for extended				
Param No.	Device	Typ.	Max.	Units	Conditions	
	Power-Down Current (IPD) ⁽¹⁾					
	PIC18LFXXK80	0.008	7	μA	-40°C	V _{DD} = 1.8V ⁽⁴⁾ (Sleep mode) Regulator Disabled
		0.013	7	μA	+25°C	
		0.035	9	μA	+60°C	
		0.218	10	μA	+85°C	
		3	12	μA	±125°C	
	PIC18LFXXK80	0.014	8	μA	-40°C	V _{DD} = 3.3V ⁽⁴⁾ (Sleep mode) Regulator Disabled
		0.034	8	μA	+25°C	
		0.092	9	μA	+60°C	
		0.312	10	μA	+85°C	
		4	16	μA	±125°C	
	PIC18FXXK80	0.2	9	μA	-40°C	V _{DD} = 3.3V (Sleep mode) Regulator Enabled
		0.23	9	μA	+25°C	
		0.32	10	μA	+60°C	
		0.51	11	μA	+85°C	
		5	18	μA	±125°C	
	PIC18FXXK80	0.22	10	μA	-40°C	V _{DD} = 5V ⁽⁵⁾ (Sleep mode) Regulator Enabled
		0.24	10	μA	+25°C	
		0.34	11	μA	+60°C	
		0.54	12	μA	+85°C	
		5	20	μA	±125°C	

Legend: Shading of rows is to assist in readability of the table.

- Note 1: The power-down current in Sleep mode does not depend on the oscillator type. Power-down current is measured with the part in Sleep mode, with all I/O pins in high-impedance state and tied to VDD or VSS, and all features that add delta current disabled (such as WDT, SOSC oscillator, BOR, etc.).
- 2: The supply current is mainly a function of operating voltage, frequency and mode. Other factors, such as I/O pin loading and switching rate, oscillator type and circuit, internal code execution pattern and temperature, also have an impact on the current consumption.
- The test conditions for all IDD measurements in active operation mode are:
 OSC1 = external square wave, from rail-to-rail; all I/O pins tri-stated, pulled to VDD;
 MCLR = VDD; WDT enabled/disabled as specified.
- 3: Standard, low-cost 32 kHz crystals have an operating temperature range of -10°C to +70°C. Extended temperature crystals are available at a much higher cost.
- 4: For LF devices, RETEN (CONFIG1L<0>) = 1.
- 5: For F devices, SRETEN (WDTCON<4>) = 1 and RETEN (CONFIG1L<0>) = 0.

7. Module: Reset (BOR)

An unexpected Reset may occur if the Brown-out Reset module (BOR) is disabled, and then re-enabled, when the High/Low-Voltage Detection module (HLVD) is not enabled (HLVDCON<4> = 0). This issue affects BOR modes: BOREN<1:0> = 10 and BOREN<1:0> = 01. In both of these modes, if the BOR module is re-enabled while the device is active, unexpected Resets may be generated.

Work around

If BOR is required and power consumption is not an issue, use BOREN<1:0> = 11. For BOREN<1:0> = 10 mode, either switch to BOREN<1:0> = 11 mode or enable the HLVD (HLVDCON<4> = 1) prior to entering Sleep. If power consumption is an issue and low power is desired, do not use BOREN<1:0> = 10 mode. Instead, use BOREN<1:0> = 01 and follow the steps below when entering and exiting Sleep.

1. Disable BOR by clearing SBOREN (RCON<6> = 0).
`WDTCONbits.SBOREN = 0;`
2. Enter Sleep mode (if desired).
`Sleep();`
3. After exiting Sleep mode (if entered), enable the HLVD bit (HLVDCON<4> = 1).
`HLVDCONbits.HLVDEN = 1;`
4. Wait for the internal reference voltage (TIRVST) to stabilize (typically 25 μ s).
`while(!HLVDCONbits.IRVST);`
5. Re-enable BOR by setting SBOREN (RCON<6> = 1).
`WDTCONbits.SBOREN = 1;`
6. Disable the HLVD by clearing HLVDEN (HLVDCON<4> = 0).
`HLVDCONbits.HLVDEN = 0;`

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

8. Module: ECAN

The enhanced window address feature, EWIN<4:0>, in the ECANCON register, will not move the BnCON 0≤n≤5 registers into the access window of RAM. The rest of the registers in B0 through B5 will be transferred into the access bank successfully. This feature is only available in Mode 1 and Mode 2; Mode 0 applications will not be affected.

Work around

1. Set the ECANCON register EWIN bits to the desired buffer.
`ECANCONbits.EWIN = Buffer_Selection;`
2. Decode the desired buffer to each individual Buffer Control register, BnCON 0≤n≤5.

```
switch (Buffer_Selection)
{
//EWIN code for Buffer B0
case 18:
    break;

//EWIN code for Buffer B5
case 23:
    break;
default:
    break;
}
```
3. Process information in the selected buffer control register. Note that the BnCON 0≤n≤5 Control registers can be set up for either transmit or receive operations.

```
case 18:
    //Save B0CON and clear flags
    being processed
    temp = B0CON;
    //clear any flags
    break;
```
4. Continue processing the rest of the buffer in the windowed location.

Affected Silicon Revisions

A2	A3	A4	A6				
X							

9. Module: MCLRE

The Master Clear pin will not be readable when MCLRE is set to off for all 28-pin part variants (PIC18F2XK80). When the MCLRE bit, CONFIG3H<7>, is cleared on the 28-pin devices, the MCLR pin will be disabled but input data will not be available on RE3.

Work around

None.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

10. Module: Timer1/Timer3

Timer1 and Timer3 gate control will not function up to the speed of Fosc when the TxCON is set to the system clock (TxCON<7:6> = 01). Results will always be at the resolution of Fosc/4, although the internal Fosc has been selected as the clock source.

Work around

Use the external clock input pin setting, TxCON<7:6> = 10 and TxCON<3> = 0.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X						

11. Module: Timer1/Timer3

When Timer1 or Timer3 is operated in Asynchronous External Input mode, unexpected interrupt flag generation may occur if an external clock edge arrives too soon following a firmware write to the TMRxH:TMRxL registers. An unexpected interrupt flag event may also occur when enabling the module or switching from Synchronous to Asynchronous mode.

Work around

This issue only applies when operating the timer in Asynchronous mode. Whenever possible, operate the Timer module in Synchronous mode to avoid spurious timer interrupts.

If Asynchronous mode must be used in the application, potential strategies to mitigate the issue may include any of the following:

- Design the firmware so it does not rely on the TMRxIF flag or keep the respective interrupt disabled. The timer still counts normally and does not reset to 0x0000 when the spurious interrupt flag event is generated.
- Design the firmware so that it does not write to the TMRxH:TMRxL registers or does not periodically disable/enable the timer, or switch modes. Reading from the timer does not trigger the spurious interrupt flag events.
- If the firmware must use the timer interrupts and must write to the timer (or disable/enable, or mode switch the timer), implement code to suppress the spurious interrupt event, should it occur. This can be achieved by following the process shown in [Example 1](#).

EXAMPLE 1: ASYNCHRONOUS TIMER MODE WORK AROUND TO AVOID SPURIOUS INTERRUPT

```
//Timer1 update procedure in asynchronous mode
//The code below uses Timer1 as example

T1CONbits.TMR1ON = 0;           //Stop timer from incrementing
PIE1bits.TMR1IE = 0;           //Temporarily disable Timer1 interrupt vectoring
TMR1H = 0x00;                   //Update timer value
TMR1L = 0x00;
T1CONbits.TMR1ON = 1;           //Turn on timer

//Now wait at least two full T1CKI periods + 2TCY before re-enabling Timer1 interrupts.
//Depending upon clock edge timing relative to TMR1H/TMR1L firmware write operation,
//a spurious TMR1IF flag event may sometimes assert. If this happens, to suppress
//the actual interrupt vectoring, the TMR1IE bit should be kept clear until
//after the "window of opportunity" (for the spurious interrupt flag event has passed).
//After the window is passed, no further spurious interrupts occur, at least
//until the next timer write (or mode switch/enable event).

while(TMR1L < 0x02);           //Wait for 2 timer increments more than the Updated Timer
                                //value (indicating more than 2 full T1CKI clock periods elapsed)
NOP();                          //Wait two more instruction cycles
NOP();

PIR1bits.TMR1IF = 0;           //Clear TMR1IF flag, in case it was spuriously set
PIE1bits.TMR1IE = 1;           //Now re-enable interrupt vectoring for timer 1
```

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

12. Module: Primary Oscillator (XT Mode)

On some parts, using the XT oscillator at the top end of its specified frequency range (3.0-4.0 MHz) may cause the part to cease driving the oscillator.

Work around

Use the XT mode only for frequencies lower than 3.0 MHz.

Use the HS mode if frequencies greater than 4.0 MHz on a crystal oscillator are required.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X					

13. Module: ECAN

When the ECAN module is placed into Disable/Sleep mode, the CANTX pin will revert to being controlled by the PORTx/TRISx/LATx registers, instead of staying in the recessive state as intended.

Work around

If Disable/Sleep mode of the ECAN is to be used, set the TRIS bit associated with the TX pin (either TRISB2 if the CANMX Configuration bit is set, TRISC6 if the CANMX Configuration bit is cleared on the 28-pin and 40/44-pin packages, or TRISE4 if the CANMX Configuration bit is cleared on 64-pin packages) and ensure that the CANTX line has a proper pull up to VDD. This will ensure that, when the pin is controlled by TRIS/LAT settings, it will be pulled to the CAN Recessive state and not cause issues on the CAN bus.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

14. Module: ECAN

A very small number of CAN applications are experiencing a low-failure rate when the microcontroller core is clocked by an oscillator through a PLL (either the PLLCFG bit is cleared or the PLEN bit of OSCTUNE is set) and the ECAN module is clocked by the same clock without a PLL (the CLKSEL bit of CIOCON is set). This failure mechanism is characterized by incoming CAN messages rarely being missed, with the ECAN module acknowledging the incoming message on the bus but not triggering interrupts or transferring the incoming data into the receive buffers.

Work around

If it is essential that the application never misses a message, it is recommended that both the ECAN module and the microcontroller be clocked either through the PLL or without a PLL. This can be achieved by ensuring that the CLKSEL bit of CIOCON remains cleared.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

15. Module: EUSART

EUSART Receive Interrupt

If the following conditions are met:

- EUSART receive interrupt is enabled (RCIE = 1)
- EUSART is disabled (SPEN = 0) as the Receive Interrupt (RCIF) is set within the same clock cycle.
- Next instruction is a function call (CALL function).

The called function will be executed twice.

Work around

Disable the Receive Interrupt prior to turning off the EUSART module.

Affected Silicon Revisions

A2	A3	A4	A6				
X	X	X	X				

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS30009977G):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Register 23-3

Register 23-3 is missing a note pertaining to the configuration of the A/D Acquisition Time selection bits. The updated register with this note is shown below:

REGISTER 23-3: ADCON2: A/D CONTROL REGISTER 2

R/W-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
ADFM	—	ACQT2	ACQT1	ACQT0	ADCS2	ADCS1	ADCS0
bit 7							bit 0

Legend:

R = Readable bit

W = Writable bit

U = Unimplemented bit, read as '0'

-n = Value at POR

'1' = Bit is set

'0' = Bit is cleared

x = Bit is unknown

bit 7 ADFM: A/D Result Format Select bit

1 = Right justified

0 = Left justified

bit 6 Unimplemented: Read as '0'

bit 5-3 ACQT<2:0>: A/D Acquisition Time Select bits⁽²⁾

111 = 20 TAD

110 = 16 TAD

101 = 12 TAD

100 = 8 TAD

011 = 6 TAD

010 = 4 TAD

001 = 2 TAD

000 = 0 TAD⁽¹⁾

bit 2-0 ADCS<2:0>: A/D Conversion Clock Select bits

111 = FRC (clock derived from A/D RC oscillator)⁽¹⁾

110 = FOSC/64

101 = FOSC/16

100 = FOSC/4

011 = FRC (clock derived from A/D RC oscillator)⁽¹⁾

010 = FOSC/32

001 = FOSC/8

000 = FOSC/2

Note 1: If the A/D FRC clock source is selected, a delay of one Tcy (instruction cycle) is added before the A/D clock starts. This allows the SLEEP instruction to be executed before starting a conversion.

2: When ACQT<2:0>=000, ADC saturation may occur due to the short period of discharging time. Use ACDT<2:0>!=000 to improve this situation for accurate measurement.

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (2/2011)

Initial release of this document; issued for revision, A2. Includes silicon issues 1 (Analog-to-Digital Converter), 2 (EUSART), 3 (ECCP), 4 (ECAN), 5 (Ultra Low-Power Sleep) and 6 (IPD and IDD).

Rev B Document (4/2011)

Added silicon issues 7 (Reset – BOR) and 8 (ECAN). Added data sheet clarifications 1, 2 (RXFCON Registers) and 3 (Listen Only Mode).

Rev C Document (9/2011)

Added [Table 3](#), 10-Bit A/D Converter Characteristics to silicon issue 1 (Analog-to-Digital Converter). Added silicon issues 9 (MCLRE) and 10 (Timer1/Timer3). Added data sheet clarifications 4 (A/D Converter Characteristics) and 5 (HLVD).

Rev D Document (12/2011)

Added silicon revision A4; includes issues 1 (Analog-to-Digital Converter – A/D), 3 (ECCP), 7 (Reset – BOR) issues 9 (MCLRE). Added data sheet clarification 6 (Power-up Timer Period).

Updated data sheet revision level to “D”. All previous clarifications carried into this revision.

Rev E Document (12/2013)

Added MPLAB X IDE; Updated silicon issue 1 (Analog-to-Digital Converter); Added silicon issue 11 (Primary Oscillator); Other minor corrections;

Data Sheet Clarifications: Added Module 7 (Electrical Characteristics) and Module 8 (A/D Converter).

Rev F Document (2/2014)

Added Silicon Revision A6; Data Sheet Clarification: Added Module 9 and 10; Other minor corrections.

Rev G Document (4/2014)

Data Sheet Clarifications: Added Module 11; Other minor corrections.

Rev H Document (7/2014)

Added Module 11, Timer1/Timer3 to Silicon errata Issues section.

Rev J Document (7/2015)

Data Sheet Clarifications: Removed the following modules, data sheet has been updated: Module 1: RXFCON Registers; Module 2: RXFCON Registers; Module 3: Listen Only Mode; Module 5: HLVD; Module 6: Power-up Timer Period. Renumbered remaining modules.

Rev K Document (04/2016)

Added Silicon Errata Issues 13 and 14. Other minor corrections.

Data Sheet Clarifications: Added Module 9 (ECAN) and Module 10 (Power-Managed Modes).

Rev L Document (01/2017)

Data Sheet Clarifications: Added Module 11 (DC Characteristics); Other minor corrections.

Rev M Document (7/2017)

Data Sheet Clarifications: Added Module 11 (A/D Converter).

Rev N Document (11/2017)

Data Sheet Clarifications: Removed all items, data sheet updated.

Rev P Document (6/2018)

Added Silicon Errata Issue 15: EUSART Receive Interrupt.

Rev Q Document (5/2023)

Added Data Sheet Clarification Module 1: Register 23-3.

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
 - Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
 - Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
 - Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.
-

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2011-2023, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-2303-8

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820