

Microchip KSZ9031RNX to LAN8830 Migration Guide

Author: John MacKay
Microchip Technology Inc.

INTRODUCTION

This document is for customers with an existing KSZ9031RNX board design migrating to the LAN8830 for their board design. This features a comparison of hardware and software register specifications between the two products. Details on the hardware and software of each device can be found on each product's Microchip web page.

[Table 1](#) summarizes the hardware attribute differences between the KSZ9031RNX and the LAN8830. [Table 2](#) summarizes the register differences between the KSZ9031RNX and the LAN8830.

TABLE 1: HARDWARE DIFFERENCES BETWEEN KSZ9031RNX AND LAN8830

Device Attribute	KSZ9031RNX	LAN8830
Analog Low Voltage	AVDDL – 1.2V	VDDAL – 1.1V
Digital Low Voltage	DVDDL – 1.2V	VDD – 1.1V
MODE Strapping Pins	<p>MODE[3:0]</p> <ul style="list-style-type: none"> – 0100: NAND Tree – 0111: Chip Power Down – 1100: RGMII mode – Advertise 1000BASE-T Full-duplex Only – 1101: RGMII mode – 1000BASE-T Full-duplex and Half-duplex only – 1110: RGMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex – 1111: RGMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex) 	<p>MODE[4:0]</p> <ul style="list-style-type: none"> – 00100: NAND Tree – 00111: Device Power Down mode – 01000: Chip Power Down – PLL Enabled – 01001: Chip Power Down – PLL Disabled – 10010: RGMII mode - Advertise 1000BASE-T Full-duplex and Half-duplex Only, EEE Disabled – 11010: RGMII mode – Advertise 1000BASE-T Full-duplex and Half-duplex only, EEE Enabled – 10000: RGMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex, EEE Disabled – 11000: RGMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex, EEE Disabled <p>Note that there is no migration from KSZ9031RNX to LAN8830, which includes 1000 Mbps Half-duplex capability (LAN8830 does not advertise 1000 Mbps Half-duplex).</p>
PME	Register setting (MMD 2.2) brings PME signal on either PME_N1 or PME_N2	Register setting sets PME on any of the GPIOs.

AN4743

TABLE 1: HARDWARE DIFFERENCES BETWEEN KSZ9031RNX AND LAN8830

Device Attribute	KSZ9031RNX	LAN8830
ALL-PHYAD	No functionality	Pin 13 can be set to respond to the LAN8830 PHY Address (from PHYAD[3:0]) and PHY Address 0. The ALLPHYAD strap-in pin is sampled and latched at power-up/Reset and are defined as follows: 0 = PHY will respond to PHY address 0 as well as its assigned PHY address 1 = PHY will respond to only its assigned PHY address.
Fast Link Failure	None	Can indicate link failure in 1 ms when enabled at 100/1000
PHYAD Strap Range	PHYAD[2:0]	PHYAD[3:0]
Energy Efficient Ethernet (EEE)	No functionality	Supports EEE
LED Modes	Single and Tricolor	Individual (Single), Tricolor, and Enhanced. Enhanced LED mode has more controls for LED function. LED mode strap for Individual (PU) and Tricolor (PD)
LED Polarity Control	None	LEDPOL[5:1] available
LEDs	2 LEDs (LED1, LED2)	5 LEDs (LED1, LED2, LED3, LED4, LED5)
GPIOs	None	10 GPIOs (GPIO0-GPIO 10)
Shorted-center Tap Magnetic Support	None	MAGJACK Strap
External Connector Loopback	None	Supported
Dynamic Channel Quality	No functionality	Dynamic Channel Quality features: – Mean Square Error (MSE) – Signal Quality Indicator (SQI) – Peak Mean Square Error (pMSE)
ISET Resistor	12.1 kΩ	6.04 kΩ

TABLE 2: REGISTER DIFFERENCES BETWEEN KSZ9031RNX AND LAN8830

Register	KSZ9031RNX	LAN8830
6h	Bit[6:5] – Reserved	Bit 6: Receive Next Page Location Able Bit 5: Received Next Page Storage Location
9h	Bit 8 can be set to advertise that PHY is 1000BASE-T Half-duplex capable	Bit 8 should be set to 0 to advertise that PHY is not 1000BASE-T Half-duplex capable. The LAN8830 does not support this mode.

TABLE 2: REGISTER DIFFERENCES BETWEEN KSZ9031RNX AND LAN8830

Register	KSZ9031RNX	LAN8830
12h	Bits[7:0] – For the open- or short-cable Fault detected in Bits[9:8] of this register, this 8-bit value represents the distance to the cable Fault.	Bits[7:0] – When VCT_SEL = 00, this is the data of cable diagnostics. Valid only when VCT_EN = 0. (1) If cable is normal, i.e., VCT_ST = 00, VCT_DATA don't care. (2) If cable is open or short, i.e., VCT_ST = 01 or 10, the distance to Fault is approximately $0.8 * (VCT_DATA - 22)$ (Meters) (3) If cable diagnostics failed, i.e., VCT_ST = 11, Bit[7] = 1 means invalid reflected pulse width, i.e. equal or greater than 152 ns, equal or less than 48 ns. Bit[6] = 1 means cable has signal for too long time during WAIT state. It's unusual and for debug only. Bit[5] = 1 means mask100 is detected, and no silent time window can be found for diagnostics. It means high frequency signal is found on the line. The link partner probably is in forced 100BT or 1000BT mode. Bit[4] = 1 means signals faster than NLP and FLP exist, and no silent time window can be found for diagnostics. It is unusual and for debug only. Bit[3:2] = Number of low pulses detected. If more than 3, stay at 3. Bit[1:0] = Number of high pulses detected. If more than 3, stay at 3.
13h	Bits[15:3] – Reserved Bit 2 – 1000BASE-T Link Status Bit 1 – 100BASE-TX Link Status Bit 0 – Reserved	Bits[15:2] – Reserved Bit 1 – 1000BASE-T Link Status Bit 0 – 100BASE-TX Link Status
16h	Reserved	Bits[15:12] – LED4 Configuration Bits[11:8] – LED3 Configuration Bits[7:4] – LED2 Configuration Bits[3:0] – LED1 Configuration
17h	Reserved	Bits 15, 13, [9:7], [4:2] – Reserved Bit 14 – LED Activity Output Select Bit 12 – LED Pulsing Enable Bits[11:10] – LED Blink/Pulse-Stretch Rate Bits[8:5] – LED Pulse Stretch Enables Bits[3:0] – LED Combination Disables
19h	Reserved	Bit 15 – MDIO Buffer Type Bit 14 – INT Buffer Type Bits[13:8] – LED Buffer Type Bit[7] – PME Polarity Bits[5:0] – LED Polarity
1Ah	Reserved	Bit 15 – Reserved Bit 14 – KSZ9031 LED Mode Bits[13:0] – Reserved
1Bh	Bit 15 – Jabber Interrupt Enable Bit 14 – Receive Error Interrupt Bit 13 – Page Receive Interrupt Bit 12 – Parallel Detect Fault Interrupt Bit 11 – Link Partner Acknowledgment Interrupt Bit 10 – Link Down Interrupt Bit 9 – Remote Fault Interrupt Bit 1 – Remote Fault Interrupt	Bits[15:12], 9 – Reserved Bit 11 – Energy Not Detected Interrupt Bit 10 – Energy Detected Interrupt Bit 1 – ADC FIFO Error Interrupt

AN4743

TABLE 2: REGISTER DIFFERENCES BETWEEN KSZ9031RNX AND LAN8830

Register	KSZ9031RNX	LAN8830
1Dh	Reserved	Bits[15:12], [9:8], [5:0] – Reserved Bit 11 – spd_clock_gate_override Bit 10 – spd_pll_disable Bit 7 – IO_DC_test_en Bit 6 – VOH
1Eh	Reserved	Bits[15:4], [2:0] – Reserved Bit 3 – External Loopback Enable
1Fh	Bits 8 and 1 – Reserved	Bit 8 – Enable SQE Test Bit 1 – Software Reset
Address 0, Reg. 3h	AN FLP Burst Transmit – LO	Reserved
Address 0, Reg. 4h	AN FLP Burst Transmit – HI	Reserved
Address 1, Reg. 5Ah	Bits[15:4] – Reserved Bits[3:1] – 1000BASE-T Link-Up Time Bit 0 – Reserved	Reserved
Address 2, Reg. 0h	Bits[15:5], 2, 0 – Reserved Bit 4 – LED Mode Override Bit 3 – Single LED Bit 1 – 125 MHz Clock Enable	Bits[15:5], [3:2] – Reserved Bit 4 – Single LED Bit 1 – 125 MHz Clock Enable Bit 0 – All-PHYAD Enable
Address 2, Reg. 1h	Bits[13:8] = Reserved	Bits[13:8] = LED Polarity
Address 2, Reg. 2h	Bits 14, 9, 0 – Reserved Bit 10 – PME_N2 Output Enable Bit 8 – LED1/PME_N1 Strap Override Bit 7 – Chip Power-Down Strap Override Bit 4 – NAND Tree Strap Override Bit 1 – GMII/MII Strap Override	Bits 10, 7 – Reserved Bit 14 – MagJack Strap Bit 9 – Software Power Down w/ PLL Disabled Bit 8 – Software Power Down w/ PLL Enabled Bit 4 – NAND Tree Strap Override Bit 1 – GMII/MII Strap Override Bit 0 – RGMII Mode
Address 2, Reg. 3h	Bits[15:8], [6:5], [3:2], 0 – Reserved Bit 7 – Chip Power-Down Strap Status Bit 4 – NAND Tree Strap Status Bit 1 – GMII/MII Strap Override	Bits 10, 7 – Reserved Bit 14 – MagJack Strap Status Bit 9 – Software Power Down w/ PLL Disabled Status Bit 8 – Software Power Down w/ PLL Enabled Status Bit 4 – NAND Tree Strap Override Status Bit 1 – GMII/MII Strap Status Bit 0 – RGMII Strap Status
Address 2, Reg. 4h	Bits[9:8] – Reserved	Bit 9 – Invert RXC Bit 8 – Invert TXC
Address 1C, Reg. 4h	Bits[15:11], [9:0] – Reserved Bit 10 – 10BASE-Te Mode	Reserved
Address 1C, 0Dh	Reserved	Bit 15 – LDO Enabled Bits 14:12 – LDO Reference Tune
Address 1C, Reg. 23h	Bits[15:1] – Reserved Bit 0 – Energy Detect Power Down Mode	Reserved

Additional features such as EEE, MSE/SQI and Self-Test for Frame Generation/Checking, are accessible in the Indirect Address Registers.

APPENDIX A: APPLICATION NOTE REVISION HISTORY

TABLE A-1: REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS00004743A (09-19-22)	Initial release.	

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: <http://microchip.com/support>

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-1254-4

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820