



BM83 MSPK2v1.2 Release Note

VERSION 1.2

The following are the attributes of this firmware version for specific system requirements and device settings. This release includes 3 firmware variants and is located at the following directory structure.

SPP: IS2083 Turnkey v1.2\Software\IS2083 Image\MSPK2v1.2\SPP

GFP: IS2083 Turnkey v1.2\Software\IS2083 Image\MSPK2v1.2\GFP

PBAP: IS2083 Turnkey v1.2\Software\IS2083 Image\MSPK2v1.2\PBAP

Details of these variants are discussed in BM83 application user guide.

New Features and Feature Enhancement

- Bluetooth Spec security vulnerability resolution
 - o SWEYNTTOOTH BLE vulnerabilities issues
 - o BIAS(Bluetooth Impersonation Attacks) vulnerability issue(CERT/CC VU#647177)
 - o Key Negotiation of Bluetooth(KNOB) BR/EDR Vulnerability(CERT VU#918987)
- Added New UART commands
 - o Host MCU DFU UART Command Sets
 - o AVRCP Vendor Dependent Command Sets
 - o New parameter type to Read BTM Version which include BTM FW version and DSP version details
 - o Battery Level Indication to support feature in Report Read Feature List Reply event
 - o Enable Device Into Test Mode (EDUTM) command.
 - o Re-introduced UART command to control GPIO
- New Configuration Parameters
 - o Enable AVRCP Browsing Feature (default Enable)
 - o Allow Users to Enable Device Under Test (default Disable)
 - o Auto Role Switch to BT Master (default Enable)
 - o Enable Role Switch in Link Policy (default Disable)
 - o Force As Bluetooth Slave Role (default Disable)
 - o Save MSPK Role When Connected (default Disable)
 - o MSPK Power Saving Grouping Interval
 - o Enable Concert Mode Master SPK Endless Grouping (default Disable)
 - o Allow Voice Prompt in MSPK Slave (default Disable)
- Config Tool improvement
 - o Drop down target selection(MSPK/GFP/PBAP/AT). Config tool will allow available configuration parameters to be customized.
 - o User data manipulation feature provided
- DFU process enhancement
- MBA App
 - o DSP OTA tuning scheme
- LDAC Codec Enhancement
 - o Passed with latest Sony LDAC conformance certification spec
 - o Extend media buffer to 32K Byte to meet Sony recommendation of Bluetooth high audio quality design

PBAP

- Created PBAP image and added in the release
- Resolved PABP connection issue

Google Fast Pair

- Created GFP and added in the release
- Compatible with existing MBA mobile App feature
- Include Google Fast Pair option into application layer general pairing procedure.
- New Configuration Parameters
 - o Google Fast Pair (default Enable)
 - o Google Fast Pair Model ID
 - o Google Fast Pair Private Key
 - o Google Fast Pair TX Power
 - o Battery Notification (default Disable)

Error Resolution

- Audio Issue fix
 - o EQ parameter setting timing error results in EQ mode ineffective
 - o Audio break issues under WCT or/and general A2DP mode corner cases resolved
 - o WCT volume sync under MCU mode error.
 - o Disabling MCLK, disable signal at MCLK1 pin
- Tone/ Voice Prompt issues fixed
 - o Tone play abnormal with line-in enable while powering off
 - o Maximum volume causes voice prompt and sine tone disappear
 - o Tone playing abnormal with BLE link exists
- Bluetooth connectivity issue fixed
 - o Revised profiles/ACL disconnection handling to avoid state machine transition incorrect
 - o Bluetooth stack and profile defects result in profiles connection failure
 - o SCO link handling incorrect make voice dial and voice transfer abnormal.
- Application behavior enhancement
 - o Revise power down flow. Delay PMU power down after power off DSP to avoid AMP pop noise.
 - o Revise MFB button detection for power on pairing flow
 - o Revise report battery level flow
 - o Revise audio source switching flow between A2DP and line-in result in incorrect source reported
 - o Revise CV mode charging flow to make charging curve lower down smoothly as expected.
 - o Memory leak in A2DP connection

Errata

- I2S should be configured as I2S Master for both master and slave speakers when BM83 Concert speakers configured as I2S out. I2S slave is not recommended as Audio discontinuity and unsync between master and slave speakers are observed when configured as I2S slave. There is no restriction on I2S (Master/Slave) in single speaker case.
- BM83 will try to be Bluetooth Slave role during LDAC playback:
 - ⇒ Some mobiles (e. g. Samsung S8) do not receive ACK properly BM83 is Bluetooth Master role during LDAC playback. It will cause audio break because of lower throughput. To have better performance in this circumstance, BM83 will try to be Slave role once LDAC codec is selected.
- Only support max to 2 A2DP links while A2DP LDAC decode playback:
 - ⇒ Because of above, while second ACL link was created, it would become a scatternet topology. Under this scenario, only 2 A2DP links can be served.
- Coexistence of BLE and SCO link in OTA DSP tuning:
 - ⇒ While performing "Voice" OTA DSP tuning via BLE, SCO link is created for transmitting/receiving SCO voice and the voice waveform was captured to measure DSP parameter effect. We suggest customers do not perform tuning and transmit/receive SCO voice simultaneously if BLE master and SCO receiver are not in the same device. Otherwise, BLE disconnection might be observed.
- One shot audio break occurred while using Android Phone playing A2DP music and trigger BLE connection.
 - ⇒ We observed Android phone will change Bluetooth Low Energy Connection Interval as 7.5 ms to query GATT Service Table. It will cause audio break because of lower throughput of A2DP streaming.
- A2DP / Aux-in source switch in A2DP suppress Aux-in case
 - ⇒ While configured to A2DP has higher priority than line-in, switching audio source to line-in from A2DP by MBA could not make line-in music play immediately. This is because most phone will transmit silence A2DP music after paused A2DP. Due to configured to A2DP has higher priority than line-in, the silence music is still decoding but unable heard, this make line-in music delay to play until A2DP

silence music is really terminated. The delay time is various by different phone brand. Sometimes it could be longest to more than 10 seconds.

- iPhone do not display battery level icon for Bluetooth accessory
 - ⇒ We observed iPhone do not display battery level if CoD (Class of Deive) of BM83 is 0x240414 (for minor device class is 0x14 Loudspeaker). But iPhone would display battery level if CoD of BM83 was setting to 0x240404 (for minor device class is 0x04 Wearable Headset Device).

VERSION1.0

The following are the attributes of this firmware version for specific system requirements and device settings

- OTA DFU feature enabled using MBA app(Android & iOS)
- LDAC support enabled
- MCLK can be enabled/disabled in Config Tool
- PBAP 1.2 enabled
- Digital microphone support is enabled
- AAC codec support added for MSPK
- AVRCP browsing feature enabled
- DSP OTA tuning enabled
- Software Development Kit(SDK) enabled
- SPKCommandsetTool crashing issue fixed
- BLE disconnection issue with Samsung S10E resolved
- Connection issue after connection is rejected is resolved
- Fixed BLE and Bluetooth classic disconnect when phone call is disconnected
- SW I2C driver Added

1. Document Revision History

Revision	Date	Section	Description
1	4/19/2019	Document	Initial Revision
1.1	06/30/2019	V1.0	Added v1.0 release details
1.2	05/08/2020	V1.2	Added v1.2 release details

The Microchip Website

Microchip provides online support via our website at <http://www.microchip.com/>. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to <http://www.microchip.com/pcn> and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: <http://www.microchip.com/support>.

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION,

INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A. Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN:

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit <http://www.microchip.com/quality>.



Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p>Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: http://www.microchip.com/support Web Address: http://www.microchip.com</p> <p>Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p>Austin, TX Tel: 512-257-3370</p> <p>Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p>Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p>Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p>Detroit Novi, MI Tel: 248-848-4000</p> <p>Houston, TX Tel: 281-894-5983</p> <p>Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p>Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p>Raleigh, NC Tel: 919-844-7510</p> <p>New York, NY Tel: 631-435-6000</p> <p>San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270</p> <p>Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078</p>	<p>Australia - Sydney Tel: 61-2-9868-6733</p> <p>China - Beijing Tel: 86-10-8569-7000</p> <p>China - Chengdu Tel: 86-28-8665-5511</p> <p>China - Chongqing Tel: 86-23-8980-9588</p> <p>China - Dongguan Tel: 86-769-8702-9880</p> <p>China - Guangzhou Tel: 86-20-8755-8029</p> <p>China - Hangzhou Tel: 86-571-8792-8115</p> <p>China - Hong Kong SAR Tel: 852-2943-5100</p> <p>China - Nanjing Tel: 86-25-8473-2460</p> <p>China - Qingdao Tel: 86-532-8502-7355</p> <p>China - Shanghai Tel: 86-21-3326-8000</p> <p>China - Shenyang Tel: 86-24-2334-2829</p> <p>China - Shenzhen Tel: 86-755-8864-2200</p> <p>China - Suzhou Tel: 86-186-6233-1526</p> <p>China - Wuhan Tel: 86-27-5980-5300</p> <p>China - Xian Tel: 86-29-8833-7252</p> <p>China - Xiamen Tel: 86-592-2388138</p> <p>China - Zhuhai Tel: 86-756-3210040</p>	<p>India - Bangalore Tel: 91-80-3090-4444</p> <p>India - New Delhi Tel: 91-11-4160-8631</p> <p>India - Pune Tel: 91-20-4121-0141</p> <p>Japan - Osaka Tel: 81-6-6152-7160</p> <p>Japan - Tokyo Tel: 81-3-6880-3770</p> <p>Korea - Daegu Tel: 82-53-744-4301</p> <p>Korea - Seoul Tel: 82-2-554-7200</p> <p>Malaysia - Kuala Lumpur Tel: 60-3-7651-7906</p> <p>Malaysia - Penang Tel: 60-4-227-8870</p> <p>Philippines - Manila Tel: 63-2-634-9065</p> <p>Singapore Tel: 65-6334-8870</p> <p>Taiwan - Hsin Chu Tel: 886-3-577-8366</p> <p>Taiwan - Kaohsiung Tel: 886-7-213-7830</p> <p>Taiwan - Taipei Tel: 886-2-2508-8600</p> <p>Thailand - Bangkok Tel: 66-2-694-1351</p> <p>Vietnam - Ho Chi Minh Tel: 84-28-5448-2100</p>	<p>Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p>Denmark - Copenhagen Tel: 45-4450-2828 Fax: 45-4485-2829</p> <p>Finland - Espoo Tel: 358-9-4520-820</p> <p>France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p>Germany - Garching Tel: 49-8931-9700</p> <p>Germany - Haan Tel: 49-2129-3766400</p> <p>Germany - Heilbronn Tel: 49-7131-72400</p> <p>Germany - Karlsruhe Tel: 49-721-625370</p> <p>Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p>Germany - Rosenheim Tel: 49-8031-354-560</p> <p>Israel - Ra'anana Tel: 972-9-744-7705</p> <p>Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p>Italy - Padova Tel: 39-049-7625286</p> <p>Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340</p> <p>Norway - Trondheim Tel: 47-72884388</p> <p>Poland - Warsaw Tel: 48-22-3325737</p> <p>Romania - Bucharest Tel: 40-21-407-87-50</p> <p>Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p>Sweden - Gothenberg Tel: 46-31-704-60-40</p> <p>Sweden - Stockholm Tel: 46-8-5090-4654</p> <p>UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>