
Questions and Answers Concerning MCP79XXX Serial RTCCs

*Author: Florian Gheorghe
Microchip Technology Inc.*

An RTCC is a device that is able to maintain the date and time in a system by using an external crystal. Microchip provides application notes that show how to make use of the various features of these devices. This technical brief intends to resolve several of the commonly-asked questions regarding developing and using Microchip MCP79XXX stand-alone serial interface Real-Time Clock/Calendar devices.

- Q** The registers can be read from and written to but the time does not increment. Why?
- A** The oscillator must be started by setting the ST bit in the RTCSEC register if a crystal is being used, or by setting the EXTOSC bit in the Control register, if an external clock source is used. Also, refer to the following documents: AN1365 – “*Recommended usage of Microchip Serial RTCC Devices*” (DS00001365) and AN1519 – “*Recommended crystals for Stand-Alone RTCCs*” (DS00001519).
- Q** How do I measure the oscillation frequency?
- A** A standard oscilloscope probe has too much loading and will attenuate the oscillator signals. It can sometimes be used for a short period of time (1-2 seconds) before causing the oscillator to stop. For longer measurements, it is recommended that a high-impedance probe with low capacitance be used. Configuring the device for 32 kHz output works too, though the peak-to-peak voltage cannot be measured. See sections [Output Configurations](#) and [Square Wave Output Mode](#) in the data sheet.
- Q** Does the MCP794XX support both alarms enabled at the same time?
- A** Yes, check section [Dual Alarm Operation](#) in the data sheet.
- Q** I'm using battery backup for my RTCC, but why can't I read the registers?
- A** The communication bus (I²C™/SPI) is disabled when the device operates on battery backup.
- Q** I use battery backup, but the registers are reset every time there is a power loss. What should I do?
- A** The VBATEN bit in the RTCWKDAY register must be set before shutting down the main power supply.
- Q** I set the VBATEN bit in the RTCWKDAY register, but I still lose date and time when switching from VCC to battery backup.
- A** VCC may be falling too fast. It must fall slower than the fall time (TFVCC) specified in the AC Characteristics table of the MCP79XXX data sheets. A capacitor on the VCC pin, big enough to slow down the voltage drop, might be needed. Also, care must be taken when writing the RTCWKDAY register, especially in bulk data transfers, so as to not clear VBATEN.
- Q** I'm using MCP7941X which has 1 kb EEPROM. Why can't I access all of the 1024 bytes?
- A** The size of the EEPROM is not 1 kilobyte, but 1 kilobit, which means that it has only 128 bytes of EEPROM memory.
- Q** I'm having trouble with setting Time/Date registers. The values read are wrong or impossible for a calendar. What should I do?
- A** The oscillator should be stopped by clearing the ST bit in the RTCSEC register if a crystal is used, or by clearing the EXTOSC bit in the Control register if an external clock source is used; wait for it to stop (the OSCRUN bit in the RTCWKDAY register should change to 0) and then update the registers and start the oscillator again.
- Q** I'm using MCP79XX RTCC, but after several hours the time is lagging/ahead. What should I do?
- A** It is recommended to use the right crystal with the right pair of capacitors to have the least amount of error in the base frequency. See AN1519 – “*Recommended Crystals for Stand-Alone RTCCs*” (DS00001519) for a list of recommended crystals. Then, the temperature of the environment needs to be taken into account; with greater variation from +25°C, the crystal will oscillate slower. See AN1413 – “*Temperature Compensation of a Tuning Fork Crystal Based on MCP79410*” (DS01413) for more details. Also, the time in the RTCC needs to be compared to a more reliable source, such as GPS or NTP.

TB3116

- Q** The crystal recommended in the data sheet is obsolete. Can you recommend another crystal that works with Microchip RTCCs?
- A** For a list of recommended crystals, refer to application note AN1519 – “*Recommended Crystals for Stand-Alone RTCCs*” (DS00001519).
- Q** Will a battery drain if I set the VBATEN bit and still power my device from VCC?
- A** No. The VBATEN bit enables the device to automatically switch to backup power when VCC falls below VTRIP, but does not increase current consumption from VBAT when operating from VCC. However, the user must still take into account the self-discharge effects of the battery.
- Q** If the ST bit in the RTCSEC register is set, but the oscillator stops for whatever reason, will the OSCRUN bit be cleared?
- A** Yes, the OSCRUN bit is set by hardware after 32 oscillator cycles are detected, and is automatically cleared if no cycles are detected after oscillator timeout period (TOSF). See the TOSF parameter in the data sheet.
- Q** What is the procedure to restart the oscillator if it stopped because of an unknown/external perturbation?
- A** If the ST bit in the RTCSEC register is still set, just remove the external perturbation that interferes with the crystal and it will begin to oscillate automatically.
- Q** Do I have to use pull-up resistors from SDA and SCL lines to the battery line?
- A** No. the I²C interface is disabled when VCC is below VTRIP.

APPENDIX A: REVISION HISTORY

Revision A (August 2014)

Original release of this document.

TB3116

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, flexPWR, JukeBlox, KEELOQ, KEELOQ logo, Klear, LANCheck, MediaLB, MOST, MOST logo, MPLAB, OptoLyzer, PIC, PICSTART, PIC³² logo, RightTouch, SpyNIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

The Embedded Control Solutions Company and mTouch are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, ECAN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, KlearNet, KlearNet logo, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, RightTouch logo, REAL ICE, SQI, Serial Quad I/O, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademarks of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2014, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-63276-519-2

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949 ==

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110

Canada - Toronto
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2943-5100
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-8792-8115
Fax: 86-571-8792-8116

China - Hong Kong SAR
Tel: 852-2943-5100
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8864-2200
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-3019-1500

Japan - Osaka
Tel: 81-6-6152-7160
Fax: 81-6-6152-9310

Japan - Tokyo
Tel: 81-3-6880-3770
Fax: 81-3-6880-3771

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Dusseldorf
Tel: 49-2129-3766400

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Pforzheim
Tel: 49-7231-424750

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Venice
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Poland - Warsaw
Tel: 48-22-3325737

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820

03/25/14