

## LAN8740A/LAN8740Ai Silicon Errata and Data Sheet Clarification

This document describes known anomalies for functional revision A and B of the LAN8740A/LAN8740Ai device. The functional revision can be determined by its top marking as indicated in [Figure 1](#) and [Figure 2](#).

**TABLE 1: HARDWARE ERRATAS SUMMARY**

| HARDWARE<br>FUNCTIONAL REV |   | DESCRIPTION                                                                                                                                      |
|----------------------------|---|--------------------------------------------------------------------------------------------------------------------------------------------------|
| A                          | B |                                                                                                                                                  |
| X                          | X | <a href="#">Section Module 1 :</a> "EEE Mode Link Failures with Cables Greater than 100m"                                                        |
| X                          | X | <a href="#">Section Module 2 :</a> "EEE Mode Link Drops with BCM53125 Link Partner for Cables Less than 20m"                                     |
| X                          |   | <a href="#">Section Module 3 :</a> "EEE Mode Drops Link with Devices that Do Not Meet the Minimum IEEE 802.3az Transmit Wake Time Specification" |
| X                          |   | <a href="#">Section Module 4 :</a> "Cable Diagnostics Incorrectly Returns "Open" Cable Condition for Terminated Cable"                           |
| X                          | X | <a href="#">Section Module 5 :</a> "EEE Mode Link Drops with Realtek RTL8305N or RTL8309E Link Partners"                                         |

**Note:** X = Applicable to the Functional Rev.

For the purposes of this anomaly sheet, the part number indicated throughout the document includes an "A". Though only functional revision B parts contain an "A" in the device part number, this anomaly sheet also applies to the LAN8740 parts. The "A" in the part number is not indicative of the functional revision. Refer to [Figure 1](#) and [Figure 2](#) for the proper identification of the functional revision of a given device.

# LAN8740A/LAN8740AI

FIGURE 1: TOP MARKING FOR FUNCTIONAL REVISION A DEVICE





FIGURE 2: TOP MARKING FOR FUNCTIONAL REVISION B DEVICE



**Note:** Figure 1 and Figure 2 detail the top markings of example parts. Other than the highlighted revision marking, other top marking values may differ (manufacture date, lot codes, industrial temperature part, etc.)

## Module 1: IEEE Mode Link Failures with Cables Greater than 100m

### DESCRIPTION

In IEEE mode, the device may fail to link or drop link at cable lengths exceeding the IEEE 802.3 specification of 100 meters.

### END USER IMPLICATIONS

When in IEEE mode, the device may either fail to link or will drop link when using cable lengths greater than the IEEE 802.3 specification of 100 meters. This anomaly does not impact 10Mb or non-IEEE operation.

#### Work around

When using IEEE mode, limit cable length to 100 meters or less.

### PLAN

This will not be addressed in a future revision of the device.

## Module 2: IEEE Mode Link Drops with BCM53125 Link Partner for Cables Less than 20m

### DESCRIPTION

In IEEE mode, the device may drop link when using a Broadcom BCM53125 link partner at cable lengths less than 20 meters.

### END USER IMPLICATIONS


When using a Broadcom BCM53125 link partner in IEEE mode, the device may drop link when using cable lengths less than 20 meters. The BCM53125 has exhibited a sensitivity to minute deviations in its link partner's transmit clock frequency during 100Mb IEEE operation. This issue is exacerbated at short cable lengths. This anomaly does not impact 10Mb or non-IEEE operation.

#### Work around

There are three methods to reduce the likelihood of occurrence:

1. Utilize an Ethernet cable length of greater than 20m.
2. Increase the load capacitors on the LAN8740A/LAN8740Ai external crystal circuit to 39pF and exercise best practices for board layout. Refer to [FIGURE 3](#): for an example external crystal circuit.

**FIGURE 3: EXAMPLE EXTERNAL CRYSTAL CIRCUIT**



3. Use a single-ended 25MHz clock source that meets the LAN8740A/LAN8740Ai specification requirements in lieu of a crystal.

### PLAN

This will not be addressed in a future revision of the device.

# LAN8740A/LAN8740AI

---

## Module 3: **EEE Mode Drops Link with Devices that Do Not Meet the Minimum IEEE 802.3az Transmit Wake Time Specification**

### DESCRIPTION

The LAN8740A/LAN8740Ai will not maintain link with devices that do not meet the minimum IEEE 802.3az transmit wake time specification.

### END USER IMPLICATIONS

The device will drop link when entering EEE mode. This does not impact 10Mb or non-EEE operation.

#### **Work around**

The following sequence of PHY register writes may be used as a work-around:

Write PHY Register 0x00: 0x2100

Write PHY Register 0x14: 0x0000

Write PHY Register 0x14: 0x0000

Write PHY Register 0x14: 0x0000

Write PHY Register 0x14: 0x0400

Write PHY Register 0x14: 0x0000

Write PHY Register 0x14: 0x0400

Write PHY Register 0x17: 0x1002

Write PHY Register 0x14: 0x4C00

Write PHY Register 0x17: 0x18BC

Write PHY Register 0x14: 0x4C03

Write PHY Register 0x17: 0x017C

Write PHY Register 0x14: 0x4C04

Write PHY Register 0x17: 0x017C

Write PHY Register 0x14: 0x4C05

Write PHY Register 0x17: 0x017C

Write PHY Register 0x14: 0x4C06

Write PHY Register 0x17: 0x0610

Write PHY Register 0x14: 0x4C08

Write PHY Register 0x17: 0x0270

Write PHY Register 0x14: 0x4C07

Write PHY Register 0x17: 0x0088

Write PHY Register 0x14: 0x4C09

Write PHY Register 0x17: 0x66FF

Write PHY Register 0x14: 0x4C0A

Write PHY Register 0x00: 0x3100

This work-around does not impact interoperability with other IEEE 802.3az compliant devices.

### PLAN

This anomaly has been fixed in functional revision B and newer devices.

## Module 4: Cable Diagnostics Incorrectly Returns “Open” Cable Condition for Terminated Cable

### DESCRIPTION

The TDR Control/Status register bits [10:9] (TDR Channel Cable Type) return 10b indicating an “Open” condition when the cable is properly terminated (connected to a link partner). For a properly terminated cable, this field should return 11b (Match condition).

### END USER IMPLICATIONS

The TDR does not return 11b for a properly terminated cable. Short and Open conditions are detected and reported correctly. There are no functional implications associated with this anomaly.

#### Work around

The following sequence of PHY register writes may be used as a work-around:

Write PHY Register 0x18: 0x9B9D

Write PHY Register 0x0D: 0x001E

Write PHY Register 0x0E: 0x000B

Write PHY Register 0x0D: 0x401E

Write PHY Register 0x0E: 0x0249

Write PHY Register 0x0D: 0x001E

Write PHY Register 0x0E: 0x000C

Write PHY Register 0x0D: 0x401E

Write PHY Register 0x0E: 0x0132

### PLAN

This anomaly has been fixed in functional revision B and newer devices.

## Module 5: EEE Mode Link Drops with Realtek RTL8305N or RTL8309E Link Partners

### DESCRIPTION

In 100Mb EEE mode, the device may infrequently drop link during continuous high-traffic operation when linked to the Realtek RTL8305N or RTL8309E devices.

### END USER IMPLICATIONS

When using a Realtek RTL8305N or RTL8309E link partner in 100Mb EEE mode, the device may drop link during continuous high-traffic operation. It is unlikely that this behavior will create any user-visible interference to the operation of applications anticipated for the device. This anomaly does not impact 10Mb or non-EEE operation.

#### Work around

No solution is required.

### PLAN

This will not be addressed in a future revision of the device.

# LAN8740A/LAN8740AI

---

## APPENDIX A: LAN8740A/LAN8740Ai DOCUMENT REVISION HISTORY

| REVISION LEVEL AND DATE | DESCRIPTION                                                                                                                                                                                                                                    |
|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| DS80000677A (12-3-15)   | Rev A replaces the previous SMSC version Rev. 1.2                                                                                                                                                                                              |
| Rev. 1.2 (06-03-13)     | Added functional revision B information.                                                                                                                                                                                                       |
|                         | Added <a href="#">Section Module 5</a> :, "EEE Mode Link Drops with Realtek RTL8305N or RTL8309E Link Partners"                                                                                                                                |
| Rev. 1.1 (10-17-12)     | Updated <a href="#">Section Module 4</a> :, "Cable Diagnostics Incorrectly Returns "Open" Cable Condition for Terminated Cable," on page 5 including solution information. Co-branded document with Microchip logo, modified legal disclaimer. |
|                         | Updated <a href="#">Section Module 3</a> :, "EEE Mode Drops Link with Devices that Do Not Meet the Minimum IEEE 802.3az Transmit Wake Time Specification," on page 4 solution information                                                      |
|                         | Updated <a href="#">Section Module 2</a> :, "EEE Mode Link Drops with BCM53125 Link Partner for Cables Less than 20m," on page 3 including end user implications and solution information                                                      |
|                         | Updated <a href="#">Section Module 1</a> :, "EEE Mode Link Failures with Cables Greater than 100m," on page 3                                                                                                                                  |
| Rev. 1.0 (05-14-12)     | Initial release                                                                                                                                                                                                                                |

## THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at [www.microchip.com](http://www.microchip.com). This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at [www.microchip.com](http://www.microchip.com). Under "Support", click on "Customer Change Notification" and follow the registration instructions.

## CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

**Technical support is available through the web site at: <http://microchip.com/support>**

# LAN8740A/LAN8740AI

---

## Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

## Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, flexPWR, JukeBlox, KEELOQ, KEELOQ logo, Kleer, LANCheck, MediaLB, MOST, MOST logo, MPLAB, OptoLyzer, PIC, PICSTART, PIC<sup>32</sup> logo, RightTouch, SpyNIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

The Embedded Control Solutions Company and mTouch are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, ECAN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, KleerNet, KleerNet logo, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, RightTouch logo, REAL ICE, SQI, Serial Quad I/O, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2015, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN:

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**= ISO/TS 16949 =**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



---

## Worldwide Sales and Service

---

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110

**Canada - Toronto**  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon

**Hong Kong**  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Hangzhou**  
Tel: 86-571-8792-8115  
Fax: 86-571-8792-8116

**China - Hong Kong SAR**  
Tel: 852-2943-5100  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8864-2200  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-3019-1500

**Japan - Osaka**  
Tel: 81-6-6152-7160  
Fax: 81-6-6152-9310

**Japan - Tokyo**  
Tel: 81-3-6880-3770  
Fax: 81-3-6880-3771

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-5778-366  
Fax: 886-3-5770-955

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7828

**Taiwan - Taipei**  
Tel: 886-2-2508-8600  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Dusseldorf**  
Tel: 49-2129-3766400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Venice**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Poland - Warsaw**  
Tel: 48-22-3325737

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820

07/14/15