

## **Global Change Notification (GCN)**

Product Family	6.2 W/W TPA / 7.3 W/W TPA	10695715	
		GCN Number	
Series	35150	June 26, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	The purpose of this letter is to inform you that copy mold for 351500290, 351500292, 351500293, 351500294, 351500296, 351500390, 351500392, 351500393, 351500394 and 351500396 will be implemented. This additional tooling is needed in order to keep up with current and future demands of this product. There will be no change in product form, fit, or function. Implementation Date may be changed due to customer demand and production situation.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	nail message.	
Reason For Short Notice Exception	New Capacity		
Assessment Of Change (How Product Will Be Qualified & Validated)	No impact to fit, form or function as a result of this change. Test report can be supplied at your request and can be communicated through your local Molex Sales Representative.		
Internal Molex Qualification Date (Planned Date Information Available)	June 15, 2015		
Sample Availability Date (Changed Part)	June 15, 2015		
Date of Implementation	July 26, 2015		
Method of Identifying Change	Lot Information in the label		
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com