SAFETY DATA SHEET

Soder-Wick Lead-Free Desoldering Braid

1. Identification of the substance/preparation and of the company/undertaking

Identification of the substance or preparation

Product name : Soder-Wick Lead-Free Desoldering Braid

Use of the substance/preparation : Desoldering

Company/undertaking identification Manufacturer : ITW Chemtronics

8125 Cobb Center Drive Kennesaw, GA 30152

Supplier

Importer : ITW Chemtronics

Rocol House Swillington Leeds **LS26 8BS** United Kingdom +44 (0) 1132322625

Emergency telephone number : Chemtrec - Call Collect 703-527-3887

2. Composition/information on ingredients

Substance/Preparation : Substance

Ingredient Name	CAS number	%	EC Number	Classification
Rosin	8050-09-7	2-10	232-475-7	R43
See Section 16 for the full text of the R Phrases declared above				

^{*} Occupational Exposure Limit(s), if available, are listed in Section 8

Hazards identification 3.

The substance is classified as dangerous according to Directive 67/548/EEC and its amendments.

Classification : R43

Human health hazards : May cause sensitisation by skin contact. See Section 11 for more detailed information on health effects and symptoms.

4. First aid measures

First aid measures

Inhalation

: If inhaled, remove to fresh air. If breathing is difficult, give oxygen. If not breathing, give

artificial respiration. Obtain medical attention.

Ingestion : Do NOT induce vomiting unless directed to do so by medical personnel. Never give anything

by mouth to an unconscious person. If large quantities of this material are swallowed, call a

physician immediately.

Skin Contact In case of contact, immediately flush skin copiously with water for at least 15 minutes while

removing contaminated clothing and shoes. Wash clothing before reuse. Clean shoes

thoroughly before reuse. Obtain medical attention immediately.

In case of contact, immediately flush eyes with a copious amount of water for at least 15 Eye contact

minutes. Get medical attention if irritation occurs.

Specific treatments

See Section 11 for more detailed information on health effects and symptoms.

5. Fire-fighting measures

Extinguishing media

: In case of fire, use water spray (fog), foam or dry chemicals.

Special exposure hazards

: No specific hazard. Not available.

fire-fighters

Special protective equipment for : Fire-fighters should wear self-contained positive pressure breathing apparatus (SCBA) and full turnout gear.

: 3/4/2005. Page: 1/3 Date of issue

6. Accidental release measures

Personal Precautions

: Immediately contact emergency personnel. Keep unnecessary personnel away. Use suitable protective equipment (Section 8). Follow all fire fighting procedures (Section 5).

Environmental precautions and

cleanup methods

: Minimize contact of spilled material with soils to prevent runoff to surface waterways. See

Section 13 for Waste Disposal Information.

If emergency personnel are unavailable vacuum or carefully scoop up spilled materials and

place in an appropriate container for disposal. Avoid creating dusty conditions and prevent wind dispersal

Note: See section 8 for personal protective equipment and section 13 for waste disposal.

7. Handling and storage

Handling: Avoid contact with skin and clothing. Wash thoroughly after handling.

Storage : Keep container tightly closed. Keep container in a cool, well-ventilated area.

Packaging materials

Recommended : Use original container.

Specific uses :

8. Exposure controls/personal protection

Exposure limit values : Not available

Exposure controls

Occupational exposure

controls

: Good general ventilation should be sufficient to control airborne levels.

Respiratory protection

: A respirator is not needed under normal and intended conditions of product use.

Hand protection

: Use chemical resistant, impervious gloves.

Eye protection

: Safety glasses.

Skin protection

: Additional body garments should be used based upon the task being performed (e.g., sleevelets, apron, gauntlets, disposable suits) to avoid exposed skin surfaces. Appropriate techniques should be used to remove potentially contaminated clothing.

9. Physical and chemical properties

General information

Appearance

Physical state : Solid.
Colour : Copper
Odour : wood rosir
Important health, safety and environmental information

pH : Not applicable.
Flash point : Not available.

Explosive properties : Not considered as a product presenting risks of explosion.

Oxidising properties : Not available.

Relative density : The only known value is 2.6 g/cm² (Rosin).

Solubility : Insoluble in cold water, hot water.

Other information

10. Stability and reactivity

Stability : The product is stable.

11. Toxicological information

Potential Acute Health Effects

Inhalation: No specific hazard.Ingestion: No specific hazard.

Skin Contact : May cause sensitisation by skin contact.

Eye contact : No specific hazard.

Over-exposure signs/symptoms

Target Organs : Contains material which causes damage to the following organs: upper respiratory tract, eye,

lens or cornea.

Other adverse effects : Not available.

Date of issue : 3/4/2005. **Page: 2/3**

Soder-Wick Lead-Free Desoldering Braid

12. Ecological information

Other adverse effects

Disposal considerations

Methods of disposal

Avoid contact of spilled material and runoff with soil and surface waterways. Dispose of

according to all federal, state and local applicable regulations.

Waste Classification : Not applicable. **European Waste Catalogue**

(EWC)

Not available.

Hazardous Waste

: The classification of the product may meet the criteria for a hazardous waste

14. Transport information

International transport regulations

Regulatory information	UN number	Proper shipping name	Class	Packing group	Label	Additional Information
ADR/RID Class	Not regulated.	Not available.	Not available.	-		-
ADN Class	Not regulated.	Not available.	Not available.	-		-
IMDG Class	Not regulated.	Not available.	Not available.	-		-
IATA-DGR Class	Not regulated.	Not available.	Not available.	-		-

15. Regulatory information

EU Regulations

Hazard symbol(s)



Risk phrases : R43- May cause sensitisation by skin contact.

Safety Phrases : S2- Keep out of the reach of children.

S24- Avoid contact with skin. S37- Wear suitable gloves.

232-475-7 **Contains** : Rosin

: Classification and labelling have been performed according to EU directives 67/548/EEC, **Product Use**

1999/45/EC, including amendments and the intended use. Industrial applications

EC Statistical Classification

(Tariff Code)

: 32089091

16. Other information

Full text of R phrases referred to : R43- May cause sensitisation by skin contact.

in Sections 2 and 3 - Europe

HISTORY

Date of printing : 3/9/2005. Date of issue : 3/4/2005

: No Previous Validation. Date of previous issue

Version : 1 Prepared by

Notice to Reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above named supplier nor any of its subsidiaries assumes any liability whatsoever for the accuracy or completeness of the information contained herein.

Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.

Version Page: 3/3