# Material Safety Data Sheet SODER-WIK DESOLDERING BRAID SERIES

SODERWK 1.00 US EA 18.05.2000 MSDS\_Europe

# 1. PRODUCT AND COMPANY IDENTIFICATION

**Product Code** 

SODERWK

**Product Type** 

Preparation

**Trade Name** 

SODER-WIK NO CLEAN DESOLDERING BRAID SERIES

Manufacturer/Supplier

**ITW-Chemtronics** 

**Address** 

Rocol House

Swillington Leeds

LS26 8BS

United Kingd

**Phone Number** 

+44 (0) 1132322625

**Chemtrec Number** 

International Call collect 703-527-3887

**MSDS** data revised

22 February 2001

# 2. COMPOSITION/INFORMATION ON THE COMPONENTS

**Hazardous Components in Product for EC** 

Component Name Codes Concentration R Phrases Classification

NON-HAZARDOUS 95.00 -100.00%

**SUBSTANCE** 

GUM ROSIN 008050-09-7 1.00 -5.00% R43 Xi

232-475-7

R43 May cause sensitisation by skin contact.

## 3. HAZARD IDENTIFICATION

**Main Hazards** 

Not classified as hazardous.

Health Effects - Skin

Material may cause slight irritation on prolonged or repeated contact.

## 4. FIRST AID MEASURES

First Aid - Eyes

No specific measures necessary.

First Aid - Skin

Wash skin with soap and water.

First Aid - Ingestion

Wash out mouth with water.

# 5. FIRE FIGHTING MEASURES

## **Extinguishing Media**

Use water spray, foam, dry chemical or carbon dioxide.

**Unusual Fire and Explosion Hazards** 

This product may give rise to hazardous fumes in a fire.

MSDS\_Europe Page 1 of 3

# Material Safety Data Sheet SODER-WIK DESOLDERING BRAID SERIES

SODERWK 1.00 US EA 18.05.2000 MSDS\_Europe

# 5. FIRE FIGHTING MEASURES

#### **Protective Equipment for Fire-Fighting**

Wear self contained breathing apparatus.

# 6. ACCIDENTAL RELEASE MEASURES

#### **Spill Procedures**

Transfer into suitable containers for recovery or disposal.

#### **Personal Precautions**

No specific measures necessary.

#### **Environmental Precautions**

Prevent the material from entering drains or water courses.

# 7. HANDLING AND STORAGE

#### Handling

No specific measures necessary.

# 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

# **Occupational Exposure Standards**

NON-HAZARDOUS SUBSTANCE N/A

GUM ROSIN UK EH40: OES 0.05mg/m3 8h TWA.

UK EH40: OES 0.15mg/m3 10min TWA.

(vapor)

#### **Engineering Control Measures**

None.

#### **Respiratory Protection**

No specific measures necessary.

## **Hand Protection**

Skin protection not normally required. However, certain individuals may develop an allergic skin reaction from contact with components in this product. Sensitive individuals should wear impervious gloves to prevent skin contact.

#### **Eye Protection**

No specific measures necessary.

### **Body Protection**

Normal work wear.

# 9. PHYSICAL AND CHEMICAL PROPERTIES

## **Physical State**

Solid

Colour Pale Yellow Odour Faint

# Flash Point (PMCC) (°C/F)

Not applicable.

#### **Density**

2.6

### **Solubility in Water**

Insoluble

MSDS\_Europe Page 2 of 3

# Material Safety Data Sheet SODER-WIK DESOLDERING BRAID SERIES

SODERWK 1.00 US EA 18.05.2000 MSDS\_Europe

# 10. STABILITY AND REACTIVITY

#### Stability

Stable under normal conditions.

#### **Materials to Avoid**

- Strong oxidizers

#### **Hazardous Decomposition Products**

Combustion will generate: - oxides of carbon

# 11. TOXICOLOGICAL INFORMATION

### **Acute Toxicity**

Low order of acute toxicity.

# 12. ECOLOGICAL INFORMATION

## **Mobility**

The product is insoluble in water.

#### Persistence/Degradability

Not applicable.

## 13. DISPOSAL

### **Product Disposal**

Dispose of in accordance with all applicable local and national regulations.

# 14. TRANSPORT INFORMATION

## **UN Number**

Not Regulated

IATA

Not Regulated

# 15. REGULATORY INFORMATION

Labelling

Information

**R Frases** 

None.

S phrases

S2 Keep out of reach of children.

# 16. OTHER INFORMATION

None

MSDS\_Europe Page 3 of 3