




FUNCTION	PIN #	PIN #	FUNCTION
FRESH AIR ZERO	10	9	ANALOGUE OUTPUT
NITROGEN ZERO	8	7	SENSOR Tx (OUT)
GND	6	5	SENSOR Rx (IN)
GND	4	3	+3.3V
N/C	2	1	GND

THIS INFORMATION SUPPLIED BY GSS IS BELIEVED TO BE ACCURATE AND RELIABLE.
HOWEVER NO RESPONSIBILITY IS ASSUMED BY GSS LTD FOR ITS USE.

Document version no: 24/07/18-001