



# Product Change Notification (PCN)

PCN Number	505166	Date Issued	June 11, 2018
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	January 26, 2018		
Sample Availability Date (Changed Part)	January 26, 2018		
Planned Implementation Date	June 18, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RELEASED

### Before Change



### After Change

#### Overview

- The Serial Number format for the Part numbers listed in this PCN will change from a six digit-four digit format to an eight digit-four digit format. The reason for the change is to eliminate duplicate serial numbers from automatically occurring via SAP every year. This change will affect all P/Ns that display a Molex serial number.
- Product Impact
  - Impact to form: Serial number will have two additional digits.
  - No impact to fit or function.
- Part Number Impact
  - See attached impacted parts list.
- Samples available upon request.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505166**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

1060051001  
1060051001  
1060051002  
1060051100  
1060051602  
1060520010  
1060520040  
1060520050  
1062672001  
1062672011  
1062673000  
1062830001  
1062830003  
1062830010  
1062831001  
1062831005  
1062831010  
1062831015  
1062835001  
1062835101  
1062835102  
1062835302  
1062835302  
1062840001  
1062840003  
1062840005  
1062840010  
1062840020  
1062841001  
1062841003  
1062841005  
1062841010

**Part numbers affected:**

106005-1100
106005-16002
106283-7503